

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:
2171482

Date Received:
09/10/2012

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 74650 Contact Name: KENNETH J KUNDRIK
 Name of Operator: RIM OPERATING, INC Phone: (303) 799-9828
 Address: 5 INVERNESS DRIVE EAST Fax: (303) 799-4258
 City: ENGLEWOOD State: CO Zip: 80112 Email: KKUNDRIK@RIMOP.COM

For "Intent" 24 hour notice required, Name: LABOWSKIE, STEVE Tel: (970) 946-5073
COGCC contact: Email: steve.labowskie@state.co.us

API Number 05-083-06005-00 Well Number: 9
 Well Name: UTE TRIBAL
 Location: QtrQtr: SWSW Section: 10 Township: 33.5N Range: 20W Meridian: N
 County: MONTEZUMA Federal, Indian or State Lease Number: 14206042397
 Field Name: MARBLE WASH Field Number: 52650

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: _____ Longitude: _____
 GPS Data:
 Date of Measurement: _____ PDOP Reading: _____ GPS Instrument Operator's Name: _____
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
ISMAY	5801	5889			-5886
LOWER ISMAY	5906	5914	09/16/1967		5914

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	17+1/2	13+3/8	48	315	300	315	0	
1ST	7+7/8	5+1/2	15.5	5,983	150	5,983	0	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 26 sks cmt from 5474 ft. to 5218 ft. Plug Type: CASING Plug Tagged:
Set 71 sks cmt from 4908 ft. to 4795 ft. Plug Type: CASING Plug Tagged:
Set 150 sks cmt from 2960 ft. to 3090 ft. Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 3140 ft. with 54 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at 2080 ft. with 48 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set 262 sacks half in. half out surface casing from 365 ft. to 0 ft. Plug Tagged:

Set 20 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Plugging Date: 12/04/2007

*Wireline Contractor: _____

*Cementing Contractor: A-PLUS WELL SERVICE INC

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No

*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: KENNETH J KUNDRIK

Title: OPERATIONS ENGINEER

Date: 8/3/2012

Email: KKUNDRIK@RIMOP.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE

Date: 9/13/2012

CONDITIONS OF APPROVAL, IF ANY:

Attachment Check List

Att Doc Num	Name
2171482	FORM 6 SUBSEQUENT SUBMITTED

Total Attach: 1 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)