




02121713

Krabacher, Jay

To: Reynolds, Scott D.
Cc: King, Kevin; Andrews, David (David.Andrews@state.co.us)
Subject: RE: Request to Delay CBL-Shideler Fee 31-6DD (045-21610)



Scott:

Encana can delay the CBL on the subject well.

Regards,

Jay Krabacher

From: Reynolds, Scott D. [mailto:Scott.Reynolds@encana.com]
Sent: Friday, September 14, 2012 6:59 AM
To: Krabacher, Jay
Subject: RE: Request to Delay CBL-Shideler Fee 31-6DD

Hi Jay,

Here is the temp log.

Scott Reynolds
Drilling Engineer – South Piceance
Encana Oil & Gas (USA) Inc
O: 720.876.5255
C: 303.895.0445
F: 720.876.6255
scott.reynolds@encana.com

Take a closer look: www.encana.com

Please note: Encana offices are closed the first and third Friday of each month

From: Krabacher, Jay [mailto:Jay.Krabacher@state.co.us]
Sent: Thursday, September 13, 2012 2:20 PM
To: Reynolds, Scott D.
Cc: Andrews, David; King, Kevin
Subject: RE: Request to Delay CBL-Shideler Fee 31-6DD

Scott:

Might we be able to check the temp log?
At present there isn't one in the well-files. On an Encana ftp: site perhaps?

Regards,

Jay Krabacher

From: Reynolds, Scott D. [mailto:Scott.Reynolds@encana.com]
Sent: Thursday, September 13, 2012 2:11 PM

To: King, Kevin; Krabacher, Jay
Cc: Andrews, David
Subject: Request to Delay CBL-Shideler Fee 31-6DD

Kevin, Jay,

EnCana CBL Deferment Request

| | |
|----------------------|-----------------------------|
| Well Name: | Shideler Fee 31-6DD |
| API Number: | 05-045-21610-00 |
| Pad Name: | K31E |
| Casing Size | 7" 23# J55 LTC |
| Casing Setting Depth | 5,254' MD-RKB |
| Plug Bump Date: | 9-10-2012 |
| Plug Bump Time: | 14:50 hrs |
| Top of MV: | 4643' MD-RKB |
| Top of Gas: | n/a Below intermediate shoe |
| Designed TOC: | 3943' MD-RKB |
| Temp Log TOC: | 3200' MD-RKB |

Bradenhead Pressure Report

| Time | Bradenhead Pressure |
|----------|---------------------|
| 6 hours | 0 |
| 12 hours | 0 |
| 24 hours | 0 |
| 48 hours | 0 |
| 72 hours | 0 |

Comments:

Pumped Cement w/ No returns, 4bbls per. minute, Pump Pressure 400 to 500 psi til Last 20bbls, Pressure increase to 2,100psi Then Dropped To 1,400psi, Bumped Plug W/ 2,600psi, Held Pressure for 5min. Bled off, 2bbl Return Floats Held

Scott Reynolds

Drilling Engineer – South Piceance

Encana Oil & Gas (USA) Inc

O: 720.876.5255

C: 303.895.0445

F: 720.876.6255

scott.reynolds@encana.com

Take a closer look: www.encana.com

Please note: Encana offices are closed the first and third Friday of each month

This email communication and any files transmitted with it may contain confidential and or proprietary information and is provided for the use of the