

FORM  
5A

Rev  
06/12

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400343023

Date Received:

11/05/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100185  
2. Name of Operator: ENCANA OIL & GAS (USA) INC  
3. Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-  
4. Contact Name: RUTHANN MORSS  
Phone: (720) 876-5060  
Fax: (720) 876-6060

5. API Number 05-077-08973-00  
6. County: MESA  
7. Well Name: HITTLE CATTLE  
Well Number: 1-4H (PL1NW)  
8. Location: QtrQtr: NWNW Section: 1 Township: 10S Range: 96W Meridian: 6  
9. Field Name: PLATEAU Field Code: 69300

Completed Interval

FORMATION: CORCORAN Status: ABANDONED WELLBORE/COMPLETION Treatment Type:  
Treatment Date: 10/12/2012 End Date: 10/12/2012 Date of First Production this formation: 11/06/2008  
Perforations Top: 5100 Bottom: 8882 No. Holes: 294 Hole size: 35/100

Provide a brief summary of the formation treatment:

Open Hole: ☐

SET CBP @ 5040' WITH 2 SX CEMENT

This formation is commingled with another formation: ☐ Yes ☒ No

Total fluid used in treatment (bbl):

Max pressure during treatment (psi):

Total gas used in treatment (mcf):

Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment:

Min frac gradient (psi/ft):

Total acid used in treatment (bbl):

Number of staged intervals:

Recycled water used in treatment (bbl):

Flowback volume recovered (bbl):

Fresh water used in treatment (bbl):

Disposition method for flowback:

Total proppant used (lbs):

Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:  
Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:  
Test Method: Casing PSI: Tubing PSI: Choke Size:  
Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:  
Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production: SUBECONOMIC

Date formation Abandoned: 10/12/2012 Squeeze: ☐ Yes ☒ No If yes, number of sacks cmt

\*\* Bridge Plug Depth: 5040 \*\* Sacks cement on top: 2 \*\* Wireline and Cement Job Summary must be attached.

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: RUTHANN MORSS

Title: REGULATORY ANALYST

Date: 11/5/2012

Email: RUTHANN.MORSS@ENCANA.COM

:

### **Attachment Check List**

Att Doc Num	Name
400343023	FORM 5A SUBMITTED
400343041	WIRELINE JOB SUMMARY

Total Attach: 2 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Permit	Changed fm. status to AB since 2 sxs on top of BP	12/20/2012 8:05:33 AM

Total: 1 comment(s)