


State
Oil and Gas Cons
1120 Lincoln Street, Suite 801, Denver, CO

02121845

(303)894-2100 Fax: (303)894-2109



SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form.) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

1. OGCC Operator Number: 96850	4. Contact Name: Greg Davis	Complete the Attachment Checklist
2. Name of Operator: WPX Energy Rocky Mountain, LLC	Phone: 303-606-4071	
3. Address: 1001 17th Street, Suite 1200	Fax: 303-629-8268	OP OGCC
City: Denver State: CO Zip: 80202		
5. API Number 05-045-21127-00	OGCC Facility ID Number	Survey Plat
6. Well/Facility Name: Bosely	7. Well/Facility Number SG 442-23	Directional Survey
8. Location (Qtr/Sec, Twp, Rng, Meridian): Lot 3 Section 23-T7S-R96W 6th PM		Surface Eqpm Diagram
9. County: Garfield	10. Field Name: Grand Valley	Technical Info Page X
11. Federal, Indian or State Lease Number:		Other

General Notice

<input type="checkbox"/> CHANGE OF LOCATION: Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)	
Change of Surface Footage from Exterior Section Lines:	<input type="checkbox"/> FNL/FSL <input type="checkbox"/> FEL/FWL
Change of Surface Footage to Exterior Section Lines:	<input type="checkbox"/>
Change of Bottomhole Footage from Exterior Section Lines:	<input type="checkbox"/>
Change of Bottomhole Footage to Exterior Section Lines:	<input type="checkbox"/> attach directional survey
Bottomhole location Qtr/Sec, Twp, Rng, Mer	
Latitude	Distance to nearest property line
Longitude	Distance to nearest bldg, public rd, utility or RR
Ground Elevation	Distance to nearest lease line
	Is location in a High Density Area (rule 603b)? Yes/No
	Distance to nearest well same formation
	Surface owner consultation date:
GPS DATA:	
Date of Measurement	PDOP Reading
	Instrument Operator's Name
<input type="checkbox"/> CHANGE SPACING UNIT	
Formation	Formation Code
Spacing order number	Unit Acreage
Unit configuration	<input type="checkbox"/> Remove from surface bond
	Signed surface use agreement attached
<input type="checkbox"/> CHANGE OF OPERATOR (prior to drilling):	
Effective Date:	
Plugging Bond: <input type="checkbox"/> Blanket <input type="checkbox"/> Individual	
<input type="checkbox"/> CHANGE WELL NAME	
From:	NUMBER
To:	
Effective Date:	
<input type="checkbox"/> ABANDONED LOCATION:	
Was location ever built? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Is site ready for inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date Ready for Inspection:	
<input type="checkbox"/> NOTICE OF CONTINUED SHUT IN STATUS	
Date well shut in or temporarily abandoned:	
Has Production Equipment been removed from site? <input type="checkbox"/> Yes <input type="checkbox"/> No	
MIT required if shut in longer than two years. Date of last MIT	
<input type="checkbox"/> SPUD DATE:	
<input type="checkbox"/> REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)	
<input type="checkbox"/> SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK	
*submit cbl and cement job summaries	
Method used	Cementing tool setting/perf depth
Cement volume	Cement top
Cement bottom	Date
<input type="checkbox"/> RECLAMATION: Attach technical page describing final reclamation procedures per Rule 1004.	
Final reclamation will commence on approximately	
<input type="checkbox"/> Final reclamation is completed and site is ready for inspection.	

Technical Engineering/Environmental Notice

<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Report of Work Done
Approximate Start Date: 01/08/13	Date Work Completed:
Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)	
<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input checked="" type="checkbox"/> Request to Vent or Flare
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Repair Well
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested
<input type="checkbox"/> Casing/Cementing Program Change	<input checked="" type="checkbox"/> Other: Vent Bradenhead
	<input type="checkbox"/> E&P Waste Disposal
	<input type="checkbox"/> Beneficial Reuse of E&P Waste
	<input type="checkbox"/> Status Update/Change of Remediation Plans
	for Spills and Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Greg Davis Date: 1/5/13 Email: greg.davis@wpxoneng.com
Print Name: Greg Davis Title: Supervisor Permits


COGCC Approved: [Signature] Title: NWAE Date: 1/10/13

CONDITIONS OF APPROVAL, IF ANY:

TECHNICAL INFORMATION PAGE



FOR OGCC USE ONLY



1. OGCC Operator Number: 96850 API Number: 05-045-21127-00
 2. Name of Operator: WPX Energy Rocky Mountain, LLC OGCC Facility ID #
 3. Well/Facility Name: Bosely Well/Facility Number: SG 442-23
 4. Location (QtrQtr, Sec, Twp, Rng, Meridian): Lot 3 Section 23-T7S-R96W 6th PM

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. DESCRIBE PROPOSED OR COMPLETED OPERATIONS

SG 442-23 (API 05-045-21127) - MV Well

- 1) This is a new drill (spud 11/21/12) and has initial MV completion scheduled for Thursday 12/20/12.
- 2) Top of cement 3490'
- 3) This well does not cover 200' above the top of the MV (Prognosis Geology pick 3102')
- 4) This well does cover the top of gas (Prognosis Geology pick: 4243')
- 5) Bradenhead Pressure observed: 325 psi.

WPX would like to run a hard line to a tank and vent the bradenhead pressure for 90 days. Eventhough top of cement was called at 3490', there is still ratty cement up much higher (into the surface casing shoe). Because of this, it will be very challenging to squeeze and there is a good chance that more than one would need to be done. Therefore, in order to avoid putting unnecessary holes in the casing, I would like to request 90 days to see if the pressure starts to deplete.