

FORM  
6Rev  
12/05State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400391361

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 35080

Contact Name: Ronald Sinclair

Name of Operator: GRAND MESA OPERATING CO

Phone: (316) 265-3000

Address: 1700 N. WATERFRONT PKWY BL 600

Fax: (316) 265-3455

City: WICHITA State: KS Zip: 67206

Email: pbrewer@gmocks.com

For "Intent" 24 hour notice required,

Name: \_\_\_\_\_ Tel: \_\_\_\_\_

COGCC contact:

Email: \_\_\_\_\_

API Number 05-073-06489-00

Well Name: PUNKIN-STATE

Well Number: 1-4

Location: QtrQtr: SWSE Section: 4 Township: 10S Range: 55W Meridian: 6

County: LINCOLN

Federal, Indian or State Lease Number: \_\_\_\_\_

Field Name: WILDCAT

Field Number: 99999

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.203160

Longitude: -103.552100

GPS Data:

Date of Measurement: 03/22/2013

PDOP Reading: 2.5

GPS Instrument Operator's Name: Keith Westfall-High

Reason for Abandonment: ☒ Dry☐ Production for Sub-economic☐ Mechanical Problems☐ Other \_\_\_\_\_Casing to be pulled: ☐ Yes☒ No

Estimated Depth: \_\_\_\_\_

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details: \_\_\_\_\_

## Current and Previously Abandoned Zones

| Formation | Code | Perf. Top | Perf. Bottom | Date | Method of Isolation | Plug Depth |
|-----------|------|-----------|--------------|------|---------------------|------------|
|           |      |           |              |      |                     |            |

Total: 0 zone(s)

## Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| CONDUCTOR   | 17+1/2       | 13+3/8         | 48              | 83            | 125          | 83         | 0          | CALC   |
| SURF        | 12+1/4       | 8+5/8          | 24              | 391           | 265          | 391        | 0          | CALC   |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

|     |    |              |      |        |      |     |            |           |              |                          |
|-----|----|--------------|------|--------|------|-----|------------|-----------|--------------|--------------------------|
| Set | 40 | sks cmt from | 7586 | ft. to | 7506 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/> |
| Set | 80 | sks cmt from | 7289 | ft. to | 7209 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/> |
| Set | 40 | sks cmt from | 6626 | ft. to | 6546 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/> |
| Set | 40 | sks cmt from | 4600 | ft. to | 4520 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/> |
| Set | 40 | sks cmt from | 4050 | ft. to | 3970 | ft. | Plug Type: | OPEN HOLE | Plug Tagged: | <input type="checkbox"/> |

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 441 ft. to 341 ft. Plug Tagged: ☐

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set 5 sacks in rat hole Set 5 sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. of 8+5/8 inch casing

Plugging Date: 03/03/2013

\*Wireline Contractor: N/A

\*Cementing Contractor: Consolidated Oilwell Services

Type of Cement and Additives Used: Common Class "H"

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

\*ATTACH JOB SUMMARY

Technical Detail/Comments:

Hard copies of Logs & DST's being mailed 03/26/2013

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: Ronald N. Sinclair

Title: President

Date: \_\_\_\_\_

Email: pbrewer@gmocks.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_

Date: \_\_\_\_\_

### CONDITIONS OF APPROVAL, IF ANY:

### Attachment Check List

| Att Doc Num | Name               |
|-------------|--------------------|
| 400391699   | WELLBORE DIAGRAM   |
| 400391703   | CEMENT JOB SUMMARY |

Total Attach: 2 Files

### General Comments

| User Group | Comment | Comment Date |
|------------|---------|--------------|
|            |         |              |

Total: 0 comment(s)