



02121942

Oil and Gas Conservation
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-4100

SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form.) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

1. OGCC Operator Number: 96850	4. Contact Name: Greg Davis	Complete the Attachment Checklist OP OGCC
2. Name of Operator: WPX Energy Rocky Mountain, LLC	Phone: 303-606-4071	
3. Address: 1001 17th Street, Suite 1200	Fax: 303-629-8268	
City: Denver State: CO Zip: 80202		
5. API Number 05-045-15383-00	OGCC Facility ID Number	Survey Plat
6. Well/Facility Name: Specialty Restaurants	7. Well/Facility Number SG 422-26	Directional Survey
8. Location (Qtr/Sec, Twp, Rng, Meridian): SWNE Section 26-T7S-R96W 6th PM		Surface Eqpm Diagram
9. County: Garfield	10. Field Name: Grand Valley	Technical Info Page X
11. Federal, Indian or State Lease Number:		Other

General Notice

<input type="checkbox"/> CHANGE OF LOCATION: Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)	
Change of Surface Footage from Exterior Section Lines:	<input type="checkbox"/> FH/LFSL <input type="checkbox"/> FH/FWL
Change of Surface Footage to Exterior Section Lines:	<input type="checkbox"/>
Change of Bottomhole Footage from Exterior Section Lines:	<input type="checkbox"/>
Change of Bottomhole Footage to Exterior Section Lines:	<input type="checkbox"/> attach directional survey
Bottomhole location Qtr/Sec, Twp, Rng, Mer	
Latitude	Distance to nearest property line
Longitude	Distance to nearest bldg, public rd, utility or RR
Ground Elevation	Distance to nearest lease line
	Is location in a High Density Area (rule 603b)? Yes/No
	Distance to nearest well same formation
	Surface owner consultation date:

GPS DATA:
Date of Measurement PDOP Reading Instrument Operator's Name

<input type="checkbox"/> CHANGE SPACING UNIT	<input type="checkbox"/> Remove from surface bond
Formation Formation Code Spacing order number Unit Acreage Unit configuration	Signed surface use agreement attached

<input type="checkbox"/> CHANGE OF OPERATOR (prior to drilling):	<input type="checkbox"/> CHANGE WELL NAME
Effective Date:	From:
Plugging Bond: <input type="checkbox"/> Blanket <input type="checkbox"/> Individual	To:
	Effective Date:

<input type="checkbox"/> ABANDONED LOCATION:	<input type="checkbox"/> NOTICE OF CONTINUED SHUT IN STATUS
Was location ever built? <input type="checkbox"/> Yes <input type="checkbox"/> No	Date well shut in or temporarily abandoned:
Is site ready for inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	Has Production Equipment been removed from site? <input type="checkbox"/> Yes <input type="checkbox"/> No
Date Ready for Inspection:	MIT required if shut in longer than two years. Date of last MIT

<input type="checkbox"/> SPUD DATE:	<input type="checkbox"/> REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)
-------------------------------------	---

<input type="checkbox"/> SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK	*submit cbl and cement job summaries
Method used Cementing tool setting/perf depth Cement volume Cement top Cement bottom Date	

<input type="checkbox"/> RECLAMATION: Attach technical page describing final reclamation procedures per Rule 1004.
Final reclamation will commence on approximately <input type="checkbox"/> Final reclamation is completed and site is ready for inspection.

Technical Engineering/Environmental Notice

<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Report of Work Done
Approximate Start Date: 05/01/13	Date Work Completed:

Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)

<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Disposal
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested	<input type="checkbox"/> Status Update/Change of Remediation Plans
<input type="checkbox"/> Casing/Cementing Program Change	<input checked="" type="checkbox"/> Other: Squeeze High Wtr Producing Zones for Spills and Releases	

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Greg Davis Date: 4/22/13 Email: greg.j.davis@wpxenergy.com
Print Name: Greg Davis Title: Supervisor Permits

COGCC Approved: [Signature] Title: NWAE Date: 4/22/13

CONDITIONS OF APPROVAL IF ANY:

RECEIVED

APR 22 2013

COGCC/Rifle Office

TECHNICAL INFORMATION PAGE



FOR OGCC USE ONLY

RECEIVED
APR 22 2013
COGCC/Rifle Office

1. OGCC Operator Number: 96850 API Number: 05- 045-15383-00
2. Name of Operator: WPX Energy Rocky Mountain, LLC OGCC Facility ID #
3. Well/Facility Name: Specialty Restaurants Well/Facility Number: SG 422-26
4. Location (QtrQtr, Sec, Twp, Rng, Meridian): SWNE Section 26-T7S-R96W 6th PM

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. DESCRIBE PROPOSED OR COMPLETED OPERATIONS



Exploration and Production
Water Squeeze Procedure

Date: 4/19/2013

Wellname: SG 422-26
Location: SWNE 26 7S 96W
Field: Grand Valley
API: 05-045-15383

Prepared By: Tony Franzone
cell phone: (970) 589-1454

Surface Casing:	9-5/8" 32.3# set @ 1,205-ft
Production Casing:	4-1/2" 11.6# set @ 5,434-ft
PBTD:	5,400-ft
TOC:	1,520-ft
Tubing:	2-3/8" tbg @ 4,921-ft
MV Completions:	MV/Cameo (3,635 - 5,211 ft)
Correlate Log:	HAL CBL - 10/09/2008

Purpose: Identify and isolate high water producing zone

Proposed Procedure:

- 1 POOH w/ 2-3/8" tbg
- 2 RIH set RBP and packer and identify high water producing zone
- 3 POOH w/ packer and tubing
- 4 RIH and remediate high water producing zone with Class G cement
- 5 POOH w/ down hole equipment
- 6 Drill out cement and test to 500 psi
- 7 RIH with tubing and return to production