



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200521

PO# 223872

Date <u>5/11/12</u>	Well Owner <u>Bayswater</u>	Well No. <u>8-4</u>	Lease <u>GITTLEIN</u>
County <u>Weld</u>	State <u>Colorado</u>	Field	
Charge to <u>Ensign U.S. Drilling</u>	Charge Code		
Address <u>P.O. Box 17805</u>	(Ensign #7)		For Office Use Only
City, State <u>Denver, Colorado 80217</u>			
Pump Truck No. <u>1201</u>	Code	Bulk Truck No. <u>1217/1218</u>	Code
Type of Job	Depth	Ft. <u>876</u>	To
Surface <u>8 5/8" CSG 24"</u>	Bottom of Surface	Ft. <u>861</u>	To
Plug	Plug Landed @ <u>819</u>	Ft.	Time On <u>1045</u>
Production	Pipe Landed @ <u>861</u>	Ft.	Time On <u>Plug Down 1445</u>

Reference No	Description	Qty.	Meas.	Unit Price	Amount		
	Pump Truck Charge						
	Cement Neat ✓	610	SKS				
	Poz. Mix						
	Calcium Chloride	3%					
	Gel % Flo-Cele 1/4 #Per Sack						
	Handling Charge						
	Hauling Charge						
	Additional Cement						
	Mixing Rate 4 BPM						
	Displacement Rate 5 BPM						
	Slurry wt. 14.8-15 PPG						
	Slurry Vol 1.18 cuft ³ -SK						
	Total Slurry Vol 128.1 BBLs cement						
	Plug landed @ 725 PSI						
Remarks	Pre-Flush w/ 20 BBLs H ₂ O	Tax Reference Code	Sub Total				
	Displace w/ 52.0 BBLs H ₂ O	State CO 2.9 %	Tax				
	Circulate 5 BBLs cement	Disc.	Total				
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1201		Pump Truck		42			
1217/1218		Bulk Truck		42/42			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Jim, Adam, Jason, Tony

Received By Byron Thompson
Customer or His Agent