



Weems - DNR, Mark &lt;mark.weems@state.co.us&gt;

---

## HE6 surface casing

2 messages

---

**Belanger, Paul (Contractor)** <paul\_belanger@kindermorgan.com> Tue, Apr 30, 2013 at 8:24 AM  
To: "Mark Weems(mark.weems@state.co.us)" <mark.weems@state.co.us>, "Larry Coler (Larry.Coler@state.co.us)" <Larry.Coler@state.co.us>  
Cc: "Clayton, Bob" <Bob\_Clayton@kindermorgan.com>, "Antipas, Andrew" <Andrew\_Antipas@kindermorgan.com>

Mark and Larry

I just got a call from drilling that because of casing tallies, etc. surface casing was actually set at 2924' vs my sundry stating 2940'; I told them it should not be anything to worry about because that's the norm and we are still over 150' below the top of the Cutler given at 2760'.

Let me know if you want me to remodify the sundry and re-send with 2924' vs. 2940' – no problem on my end.  
Paul

Paul E. Belanger, Geologist  
Regulatory Contractor @ Kinder Morgan  
cell 303-249-7966  
If you need to contact someone in Cortez office  
please call 970-882-2464

---

**Weems - DNR, Mark** <mark.weems@state.co.us> Tue, Apr 30, 2013 at 8:45 AM  
To: "Belanger, Paul (Contractor)" <paul\_belanger@kindermorgan.com>  
Cc: "Larry Coler (Larry.Coler@state.co.us)" <Larry.Coler@state.co.us>, "Clayton, Bob" <Bob\_Clayton@kindermorgan.com>, "Antipas, Andrew" <Andrew\_Antipas@kindermorgan.com>

I approve and will put a copy of this email in the well file.

Mark Weems, P. E.  
Regional Engineer - SW Colorado

Colorado Oil and Gas Conservation Commission  
50 Long Hollow Lane  
Durango, CO 81301  
(970) 259-4587 office  
(970) 749-0624 cell

[Quoted text hidden]