

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial No.
COD033164A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.7. If Unit or CA/Agreement, Name and/or No.
COC48349X

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.
F WILSON 72. Name of Operator
WEXPRO COMPANYContact: RAFAEL CHAVEZ
E-Mail: Rafael.Chavez@questar.com9. API Well No.
05-081-055533a. Address
PO BOX 458 2221 WESTGATE DR.
ROCK SPRINGS, WY 829013b. Phone No. (include area code)
Ph: 307-352-7506
Fx: 307-352-757510. Field and Pool, or Exploratory
HIAWATHA FIELDS

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 23 T12N R100W Mer 6PM SWNW 1650FNL 990FWL
40.988388 N Lat, 108.606949 W Lon

11. County or Parish, and State

MOFFAT COUNTY, CO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Wexpro Company is filing this Notice of Intent to Plug and Abandon F Wilson 7. Attached is the plugging procedure and current wellbore diagram.

In conjunction with this work, Wexpro also requests approval to dig an 8'x8'x6'(LxWxD)pit to accomodate cementing cleanup.

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #219579 verified by the BLM Well Information System
For WEXPRO COMPANY, sent to the Craig**

Name (Printed/Typed) CHRIS BEILBY

Title COMPLETION MANAGER

Signature (Electronic Submission)

Date 09/10/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****