

FORM
6Rev
12/05State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400429557

Date Received:

06/05/2013

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10150

Contact Name: Jessica Donahue

Name of Operator: BLACK HILLS PLATEAU PRODUCTION LLC

Phone: (720) 210-1333

Address: 1515 WYNKOOP ST STE 500

Fax: (303) 566-3344

City: DENVER State: CO Zip: 80202

Email: Jessica.Donahue@blackhillscorp.com

For "Intent" 24 hour notice required,

Name: Tel:

COGCC contact:

Email:

API Number 05-077-08455-00

Well Name: WINTER FLATS

Well Number: 1 10 99

Location: QtrQtr: NWSW Section: 10 Township: 9S Range: 99W Meridian: 6

County: MESA

Federal, Indian or State Lease Number: 35312

Field Name: BRONCO FLATS

Field Number: 7563

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.285012

Longitude: -108.429860

GPS Data:

Date of Measurement: 05/14/2008

PDOP Reading: 2.5

GPS Instrument Operator's Name: Alan Vrooman

Reason for Abandonment: ☐ Dry ☐ Production for Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|----------------|-----------|-----------|----------------|---------------------|------------|
| CEDAR MOUNTAIN | 6939 | 7004 | | | |
| DAKOTA | 6857 | 6912 | | | |

Total: 2 zone(s)

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF | 14+3/4 | 10+3/4 | 40.5 | 322 | 355 | 322 | 0 | VISU |
| 1ST | 8+3/4 | 7 | 23 | 3,205 | 150 | 3,205 | 1,958 | CALC |
| 2ND | 6+1/4 | 4+1/2 | 11.6 | 7,118 | 150 | 7,118 | 5,964 | CALC |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6800 with 2 sacks cmt on top. CIPB #2: Depth 2055 with 10 sacks cmt on top.
CIBP #3: Depth 977 with 10 sacks cmt on top. CIPB #4: Depth 325 with 10 sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 275 sks cmt from 2050 ft. to 3205 ft. Plug Type: CASING Plug Tagged: ☐
Set 10 sks cmt from 1000 ft. to 1050 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 1052 ft. with 100 sacks. Leave at least 100 ft. in casing 977 CICR Depth

Perforate and squeeze at 380 ft. with 45 sacks. Leave at least 100 ft. in casing 325 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 30 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 0 ft. of _____ inch casing

Plugging Date: 08/20/2008

*Wireline Contractor: Mesa Wireline

*Cementing Contractor: BJ Services

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Jessica Donahue

Title: Regulatory Technician

Date: 6/5/2013

Email: Jessica.Donahue@blackhillscorp.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRABACHER, JAY

Date: 10/10/2013

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

| COA Type | Description |
|----------|-------------|
| | |

Attachment Check List

| <u>Att Doc Num</u> | <u>Name</u> |
|--------------------|-----------------------------|
| 400429557 | FORM 6 SUBSEQUENT SUBMITTED |
| 400429565 | WELLBORE DIAGRAM |
| 400429566 | WIRELINER JOB SUMMARY |
| 400429569 | CEMENT JOB SUMMARY |

Total Attach: 4 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|---------------------|
| | | |

Total: 0 comment(s)