



DEPARTMENT OF NATURAL RESOURCES  
*John W. Hickenlooper, Governor*  
1120 Lincoln St. Suite 801  
Denver, CO 80203  
Phone: (303) 894-2100  
FAX: (303) 894-2109  
[www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

Petrohunter Operating Company  
Attn: Mr. Paul Maniscalco  
1600 Stout Street, Suite 2000  
Denver, Colorado 80202-3113

September 6, 2011

Dear Mr. Maniscalco,

The Colorado Oil and Gas Conservation Commission received the four sets of Mechanical Integrity Test (MIT) forms and charts you sent last Friday, September 2. Three of the wells (listed below) failed to pass the MIT. Rule 326.d requires that Petrohunter repair or plug and abandon the wells by January 18, 2012 (within 6 months based on the test date; July 18, 2011).

Buckskin Mesa Unit #2620  
NWNE 35-1N-95W  
Rio Blanco County  
API: 103-10230

Buckskin Mesa Unit #2571  
SESW 26-1N-95W  
Rio Blanco County  
API: 103-09995

Buckskin Mesa Unit #2570  
SWSW 23-1N-95W  
Rio Blanco County  
API: 103-10001

The 4<sup>th</sup> Buckskin Mesa well, the #2574, passed the MIT but the Form 21 is incomplete. You or Scott Chipperfield are required to fill the form out completely and resubmit it to me. COGCC cannot fill in the form for you. Note; Under the Part I check boxes-this is not a 5-Year UIC Test, this is a Test to Maintain SI/TA Status.

Buckskin Mesa Unit #2574  
SESW 35-1N-95W  
Rio Blanco County  
API: 103-10062

Thank you for following through on the testing and I'm sorry so many of the wells failed the test. Please feel free to contact me if you have any questions.

Sincerely,

A handwritten signature in cursive script, appearing to read "Robert Koehler".

Robert P. Koehler  
Engineering/Environmental Technician

Telephone: 303-894-2100 x5147 Email: [Bob.Koehler@state.co.us](mailto:Bob.Koehler@state.co.us) Website:  
[www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

7008 0150 0001 7352 2441

U.S. Postal Service™  
**CERTIFIED MAIL™ RECEIPT**  
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at [www.usps.com](http://www.usps.com)

**OFFICIAL USE**

Postage	\$	Postmark Here
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$	

Sent To **PETROHUNTER /// PAUL MANISCALCO**  
 Street, Apt. No.,  
 or PO Box No. **1600 STOUT ST, STE 2000**  
 City, State, ZIP+4 **DENVER, CO 80203-3113**

PS Form 3800, August 2006

See Reverse for Instructions

**SENDER: COMPLETE THIS SECTION**

- Complete Items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

**Petrohunter Operating Co.**  
**Attn: Mr. Paul Maniscalco**  
**1600 stout St., Suite 2000**  
**Denver, CO, 80203-3113**

2. Article Number

(Transfer from service label)

7008 0150 0001 7352 2441

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature *[Signature]* ☐ Agent  
☒ Addressee

B. Received by (Printed Name)

C. Date of Delivery

**SEP 19**

D. Is delivery address different from item 1? ☐ Yes  
 If YES, enter delivery address below: ☐ No

3. Service Type

- ☒ Certified Mail ☐ Express Mail  
☐ Registered ☐ Return Receipt for Merchandise  
☐ Insured Mail ☐ C.O.D.

4. Restricted Delivery? (Extra Fee) ☐ Yes

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540