

FORM
5A

Rev
06/12

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400525886

Date Received:

12/12/2013

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 10422
2. Name of Operator: PRONGHORN OPERATING LLC
3. Address: 8400 E PRENTICE AVENUE #1000
City: GREENWOOD State: CO Zip: 80111
4. Contact Name: Jake Flora
Phone: (720) 988-5375
Fax:
Email: jakeflora@kfrcorp.com

5. API Number 05-017-07753-00
6. County: CHEYENNE
7. Well Name: Smith
Well Number: 1
8. Location: QtrQtr: SENE Section: 6 Township: 14S Range: 44W Meridian: 6
9. Field Name: CHEYENNE WELLS Field Code: 11050

Completed Interval

FORMATION: SPERGEN Status: DRY AND ABANDONED Treatment Type: ACID JOB

Treatment Date: 08/28/2013 End Date: 08/28/2013 Date of First Production this formation:

Perforations Top: 5416 Bottom: 5421 No. Holes: 20 Hole size: 01/2

Provide a brief summary of the formation treatment:

Open Hole: ☐

Pumped 500 gal 15% HCL.

This formation is commingled with another formation: ☐ Yes ☒ No

Total fluid used in treatment (bbl): 42

Max pressure during treatment (psi): 400

Total gas used in treatment (mcf): 0

Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment:

Min frac gradient (psi/ft):

Total acid used in treatment (bbl): 12

Number of staged intervals:

Recycled water used in treatment (bbl): 0

Flowback volume recovered (bbl): 45

Fresh water used in treatment (bbl): 30

Disposition method for flowback: DISPOSAL

Total proppant used (lbs):

Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 12/28/2013 Hours: 5 Bbl oil: 1 Mcf Gas: 0 Bbl H2O: 44

Calculated 24 hour rate: Bbl oil: 2 Mcf Gas: 0 Bbl H2O: 1 GOR: 0

Test Method: swab Casing PSI: 0 Tubing PSI: 0 Choke Size:

Gas Disposition: Gas Type: Btu Gas: 0 API Gravity Oil: 38

Tubing Size: 2 + 7/8 Tubing Setting Depth: 5432 Tbg setting date: 12/28/2013 Packer Depth: 5400

Reason for Non-Production: poor inflow, tight rock

Date formation Abandoned: 08/29/2013 Squeeze: ☐ Yes ☒ No If yes, number of sacks cmt

** Bridge Plug Depth: 5390 ** Sacks cement on top: 2 ** Wireline and Cement Job Summary must be attached.

Comment:

--

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jake Flora

Title: Petroleum Engineer Date: 12/12/2013 Email jakeflora@kfrcorp.com
:

Attachment Check List

Att Doc Num **Name**

400525886	FORM 5A SUBMITTED
-----------	-------------------

Total Attach: 1 Files

General Comments

User Group **Comment** **Comment Date**

--	--	--

Total: 0 comment(s)