



STATE OF COLORADO




DNR, Jay <jay.krabacher@state.co.us>

RWF 724-16 Intermediate Cement Bond Log API# 05-045-22157

1 message

Beougher, Justin <Justin.Beougher@wpxenergy.com>
To: "Krabacher - DNR, Jay" <jay.krabacher@state.co.us>



Jay,

This is the follow-up email to our conversation on 12/15/2013 between 11:45 am and 12:00 pm regarding the intermediate cement bond log on the RWF 724-16 (API 05-045-22157.) We decided that the most recent bond log showed sufficient bond to not require any remediation or a sundry regarding a low cement top. We agreed that WPX Energy was ok to continue with the normal operations of setting production casing.

If you have any issues or need more information, please don't hesitate to contact me. Thank you for taking your weekend time to work through this, it was very helpful to us.

Justin Beougher

Asset Drilling Engineer

WPX Energy Rocky Mountain, LLC

Office 303-606-4257

Cel 970-274-9250

Justin.Beougher@WPXEnergy.com

