

## WELLBORE DIAGRAM

Directions: WCR68 & WCR 59, 0.4 mile east on WCR 68, 0.5 mile S into lo

### Bayswater E & P Larson Farms 3-24

NESW Sec 24-T6N-R64W  
SHL: 2226' FSL, 2452' FWL  
BHL: 1951' FSL, 1985' FEL  
Weld County CO  
05-123-34147

Updated  
10/23/2013  
JRR

