



February 3, 2014

**Williford Resources, LLC
CINCO-DE-MAYO #1
SESW 22 33N 12W
05-067-06917**

Well File Notes prepared by,

M. E. Weems, P. E.
Regional Engineer SW Colorado
Colorado Oil and Gas Conservation Commission
Durango, CO

5/7/87 APD states

12 3/4" bit 9 5/8 csg set at 200' cmt w/ 100 sx
8 3/4 bit to TD=1500' 5 1/2 csg set at 1500' w/ no cmt and shouldered in MV formation

9/6/87 Sundry Notice states

9 5/8 csg set at 200' cmt w/ 100 sx
8 3/4 bit to 1500' 5 1/2 csg run to 1500' no cmt and shouldered on MV formation

12/1/87 Completion Report states

12 1/4 bit 9 5/8 csg set at 200' cmt w/ 100 sx
8 3/4 bit to TD=1500' 5 1/2 csg set by csg hanger to depth=1400' no cmt

1/21/2014

Drilling Completion Report states

TD=1500' as of 9/6/1987
12 1/4 bit 9 5/8 csg set at 200' cmt w/ 100 sx
Casing modification 9/08/2010
8 3/4 bit 5 1/2 csg set at 510' cmt w/ 60 sx; bottom of cmt=403' and top of cmt=surf
8 3/4 bit 4 1/2 csg hung at 510' and set at 1110' w/ no cmt
TA w/ plug set at 510' and capped w/ 11' cmt

2/3/2014

Phone conv w/ Hern Williford-President Williford Resources, LLC regarding well work done in 2010 and the recent MIT.
5 1/2 casing run from surface to 510' followed by a 5 1/2" x 4 1/2 swage and 4 1/2 csg run to a depth of 1110'
Pea gravel was dumped down the 9 5/8 x 5 1/2 annulus to fill open hole 1110'-1500'
Pea gravel top tagged at some depth below 403', the 5 1/2 casing was perforated at 403' and cement sqzed to surface.
Hern stated that an MIT was conducted and submitted to Denver COGCC
Phone conv w/ Bob Koehler
Bob states that he did receive the MIT and he had some questions regarding it and put the work on hold while tending to other assignments
I asked Hern to re-submit the MIT documentation to me, Mark Weems Regional Engineer SW Colorado

Selected Items Report

Oil and Gas Wells Selected

Filter Results by Formation

Include

Filter

WELL DESCRIPTION

LOCATION ID

LOCATION

WELL INFORMATION

Water Wells Selected From Map

Filter Results by Depth

Greater than

Filter

WELL DESCRIPTION	LOCATION	WELL INFORMATION			
		Depth	Top Perf	Bottom Perf	Aquifer
Receipt=9123553, Permit=0089064-- KENNEDY JOHN E	SWSE 15 33 N-12W	125	0	0	GW
Receipt=0310201, Permit=0156504-- HARRIS RUSSEL D	SESE 21 33 N-12W	0	0	0	GW
Receipt=0421455B, Permit=0204910-- CAMPBELL LEE	NWNE 22 33 N-12W	80	24	80	GW
Receipt=0207703, Permit=0117198--A KENNEDY J R	SENE 22 33 N-12W	10	0	0	GW
Receipt=0370555, Permit=0179941-- ENGLE HOWARD B	SENE 22 33 N-12W	10	0	0	GW
Receipt=0370556, Permit=0117198--A JEWELL LYNN	SENE 22 33 N-12W	0	0	0	GW
Receipt=9124059, Permit=0117198-- KENNEDY J. RUSSELL	SENE 22 33 N-12W	40	0	0	GW
Receipt=0395600, Permit=0192390-- BRUNNER TOM & NICOLA	SWNE 22 33 N-12W	95	25	95	GW
Receipt=0331013, Permit=0100323--A DUHS WILLIAM L	NENW 22 33 N-12W	0	0	0	GW
Receipt=9123886, Permit=0100323-- DUHS WILLIAM L & BETTY J.	NENW 22 33 N-12W	115	0	0	GW
Receipt=9703148, Permit=0285878-- SMITH HOWARD L AND SARAH R	SENE 22 33 N-12W	20	0	0	GW
Receipt=0418473, Permit=0203294-- DUHS JAMES S	SWNW 22 33 N-12W	0	0	0	GW
Receipt=0095282B, Permit=0101349-- HARRIS DONALD	NWSE 22 33 N-12W	55	0	38	GW
Receipt=0331298, Permit=0162156-- HARRIS ANGELINA G	NESW 22 33 N-12W	56	0	0	GW
Receipt=0399126, Permit=0162156--A HARRIS DONALD & ANGELINA	NESW 22 33 N-12W	0	0	0	GW
Receipt=9701414, Permit=0249806-- HARRIS RUSSELL D	NESW 22 33 N-12W	0	0	0	GW
Receipt=0214564, Permit=0119668-- DUHS WILLIAM L	NWSW 22 33 N-12W	58	22	44	GW

Receipt=9123883, Permit=0100293-- HARRIS DONALD	SWNW 23 33 N-12W	80	28	38	GW
Receipt=9700012, Permit=0225036-- YEAGER BONNIE J	SWNW 26 33 N-12W	0	0	0	GW
Receipt=9701359, Permit=0248756-- YEAGER RONALD & CARLA	SWNW 26 33 N-12W	60	20	60	GW
Receipt=9701371, Permit=0249039-- HERRERA PEDRO L	NENE 27 33 N-12W	0	0	0	GW
Receipt=9702825, Permit=0278381-- HERRERA ROGER & DEBBRA	SENE 27 33 N-12W	100	25	100	GW
Receipt=9123826, Permit=0098274-- BABCOCK DWIGHT E	NENW 27 33 N-12W	70	12	70	GW
Receipt=0349535, Permit=0168758-- HUGHES JOHNNY	NWNW 27 33 N-12W	55	20	55	GW
Receipt=0457011, Permit=0222425-- BABCOCK DWIGHT	SENW 27 33 N-12W	12	6	10	GW
Receipt=9701613, Permit=0254219-- GLADDEN BENSON	NWSW 27 33 N-12W	60	24	32	GW
Receipt=0914891, Permit=0120600-- WIGGINS JERRY W	SWSW 27 33 N-12W	0	0	0	GW
Receipt=0909685, Permit=0071685-- LEE NYAL W	28 33 N-12W	0	0	0	GW
Receipt=0449400, Permit=0219059-- WALKER RICHARD	NWNE 28 33 N-12W	0	0	0	GW
Receipt=9700948, Permit=0243470-- MCKAY JOHN H	SENE 28 33 N-12W	*360	0	0	GW
Receipt=9702532, Permit=0273747-- YOUNG SHANE	SWNE 28 33 N-12W	0	0	0	GW
Receipt=0401600, Permit=0195206-- YOUNG SHANE L	SWNE 28 33 N-12W	0	0	0	GW
Receipt=0304259, Permit=0156175-- DAVIS JACKIE	NESE 28 33 N-12W	0	0	0	GW
Receipt=0458859, Permit=0222467-- MCKAY JOHN H	SESE 28 33 N-12W	23	20	23	GW
Receipt=9700946, Permit=0251007-- MCKAY JOHN H	SESE 28 33 N-12W	23	20	23	GW

4/11/2004

McKay John H

360'

Well Construction and Test Report

States grey shale drilled from 130'-300'

Little water found

Owner needs to PA

All other water wells are shallower than the surface casing depth of 200' on the CINCO DE MAYO No 1