

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

2361645

Date Received:

04/04/2014

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 74740

Contact Name: MIKE HAYES

Name of Operator: RIO MESA RESOURCES INC

Phone: (970) 620-2257

Address: 226 1/2 E MAIN ST

Fax: (970) 675-5137

City: RANGELY State: CO Zip: 81648

Email: HAYESPETRO@CENTURYTEL.NET

For "Intent" 24 hour notice required,

Name: Covington, Dave

Tel: (970) 623-9782

COGCC contact:

Email: dave.covington@state.co.us

API Number 05-103-09102-00

Well Name: AMOCO LARSON

Well Number: 4

Location: QtrQtr: SESE Section: 26 Township: 2N Range: 102W Meridian: 6

County: RIO BLANCO

Federal, Indian or State Lease Number: 46399

Field Name: RANGELY

Field Number: 72370

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.110059

Longitude: -108.803603

GPS Data:

Date of Measurement: 08/11/2009

PDOP Reading: 2.4

GPS Instrument Operator's Name: Jonathan Leif Joy

Reason for Abandonment: ☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☒ No

Estimated Depth:

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
MANCOS	243	3172			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	8+3/4	7	23	243	32	243	0	VISU
OPEN HOLE	6			3,172				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 12 sks cmt from 60 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 20 sacks half in. half out surface casing from 293 ft. to 193 ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: MICHAEL G HAYES

Title: PARTNER Date: 3/31/2014 Email: HAYESPETRO@CENTURYTEL.NET

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: BURGER, CRAIG Date: 4/8/2014

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 10/7/2014

COA Type

Description

	Changed procedure to include 100' plug at surface casing shoe from 293' to 193'. Operator agreed to change and provided fax copy of final wellbore diagram (document #2597063). This notice of intent is approved with condition that the subsequent report of abandonment include initial and final wellbore diagrams.
--	---

Attachment Check List

Att Doc Num**Name**

2361645

FORM 6 INTENT SUBMITTED

Total Attach: 1 Files

General Comments

User Group**Comment****Comment Date**

Permit

No wellbore diagrams, sketchy cementing procedure for essentially uncased hole. Discussed with Craig Burger, called Mike Hayes, gave him Craig's phone # and told Hayes more engr type info needed. Hayes will call Burger.

All OK by me now. 4/8/14 dhs.

4/4/2014
11:08:30 AM

Total: 1 comment(s)