

FORM
6Rev
12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

2361651

Date Received:

04/07/2014

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 24320

Contact Name: DAVE PETERSON

Name of Operator: DIAMOND OPERATING, INC.

Phone: (303) 494-4420

Address: 6666 GUNPARK DR STE #200

Fax: (303) 4943931

City: BOULDER State: CO Zip: 80301

Email: DAVEP@FLATIRONENERGY.COM

For "Intent" 24 hour notice required, Name: QUINT, CRAIG Tel: (719) 767-8939

COGCC contact: Email: craig.quint@state.co.us

API Number 05-125-06339-00

Well Name: STATE OF COLORADO

Well Number: 1-12

Location: QtrQtr: SENE Section: 12 Township: 2S Range: 44W Meridian: 6

County: YUMA

Federal, Indian or State Lease Number: 73/4869-I

Field Name: BEECHER ISLAND

Field Number: 5997

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.900310 Longitude: -102.244080

GPS Data:

Date of Measurement: 09/01/2010 PDOP Reading: 2.1 GPS Instrument Operator's Name: Duane Russell

Reason for Abandonment: ☐ Dry ☐ Production for Sub-economic ☐ Mechanical Problems☒ Other COGCC MANDATECasing to be pulled: ☒ Yes ☐ No Estimated Depth: 850Fish in Hole: ☐ Yes ☒ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☒ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
NIOBRARA	1682	1700		CEMENT	

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	20	190	160	190	0	VISU
1ST	7+7/8	4+1/2	9.5	1,806	150	1,865	957	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1650 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 50 sacks half in. half out surface casing from 140 ft. to 240 ft. Plug Tagged: ☐

Set 15 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: DAVE PETERSON

Title: PRESIDENT Date: 4/4/2014 Email: DAVEP@FLATIRONENERGY.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK Date: 4/30/2014

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 10/29/2014

COA Type

Description

	Note changes to submitted form. 1) Provide 48 hour notice of MIRU via electronic Form 42. 2) Tag shoe plug. 3) Surface plug: Cement from 50' to surface.
--	---

Attachment Check List

Att Doc Num**Name**

2361650	WELLBORE DIAGRAM
2361651	FORM 6 INTENT SUBMITTED

Total Attach: 2 Files

General Comments

User Group**Comment****Comment Date**

Engineer	Increased cement quantity on shoe and surface plugs.	4/30/2014 3:35:09 PM
----------	--	-------------------------

Total: 1 comment(s)