

STATE OF  
COLORADO

Andrews - DNR, Doug &lt;doug.andrews@state.co.us&gt;

---

**COGCC Form 2A review of Extraction O&G's Winder 9-41 location - Doc #400589321**

2 messages

**Andrews - DNR, Doug** <doug.andrews@state.co.us>

Tue, May 20, 2014 at 10:21 AM

To: Regulatory members &lt;regulatory@petro-fs.com&gt;

Ann,

I have reviewed the referenced Form 2A Oil and Gas Location Assessment and have the following comments.

1) A review of your Location Drawing indicates the disturbed area will overlap across the irrigation ditches located 315 feet and 316 feet southwest. Therefore, I would like to add the following Condition of Approval to protect them:

"Operator must implement site-specific best management practices in accordance with good engineering practices, including, but not limited to, construction of a berm or diversion dike, site grading, or other comparable measures, sufficient to protect the irrigation ditches located 315 feet and 316 feet southwest of the oil and gas location from a release of drilling, completion, produced fluids, and chemical products."

2) Scott Ballstadt with the Town of Windsor has added a comment to this Form 2A indicating the subject property is located within the Town's Growth Management Area and requests that a comprehensive Drilling and Site Improvement Plans be submitted for their review and approval.

Are you aware of this comment from the Town of Windsor and is Extraction working with Windsor in the development of this oil and gas location?

Please respond to this correspondence by June 20, 2014. If you have any questions, please feel free to contact me. Thank you.

-

*Doug Andrews*

Oil &amp; Gas Location Assessment Specialist - Northeast Area

**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

1120 Lincoln St., Suite 801

Denver, CO 80203

[doug.andrews@state.co.us](mailto:doug.andrews@state.co.us)

303-894-2100 Ext. 5180

---

**Ann Stephens** <astephens@petro-fs.com>

Wed, May 21, 2014 at 3:06 PM

To: "Andrews - DNR, Doug" &lt;doug.andrews@state.co.us&gt;

Cc: Jennifer Grosshans &lt;jgrosshans@petro-fs.com&gt;

Hi Doug,

In response to your items below:

1. Operator agrees to the COA re: protection of the two ditches within the disturbed area.
2. Yes, Operator is in contact with the Town of Windsor re: their required CUG permit and are in continuing conversations with Scott Ballstadt.

Thank you for your guidance, Doug. Please advise if I may be of further assistance.

Respectfully,

**Ann Stephens**

**Regulatory Manager**

Petroleum Field Services, LLC

7535 Hilltop Circle

Denver, Colorado 80221

Office: 303-928-7128

Fax: 303-218-5678



Helping America Achieve Energy Independence

Please Follow us on Facebook, Twitter, and LinkedIn!



Confidentiality Notice: This e-mail message and attachments are only for the use of the intended recipient and may contain information that is privileged, confidential or exempt from disclosure under applicable law. If you are not the intended recipient, any disclosure, distribution or other use of this e-mail message or attachments is prohibited. If you have received this e-mail in error, please delete and notify the sender immediately. In addition, please be aware that any messages addressed to our domain are subject to archiving and review by persons other than the intended recipient.



Please recycle and consider the environment before printing this email.

**From:** Andrews - DNR, Doug [mailto:[doug.andrews@state.co.us](mailto:doug.andrews@state.co.us)]

**Sent:** Tuesday, May 20, 2014 10:21 AM

**To:** Regulatory members

**Subject:** COGCC Form 2A review of Extraction O&G's Winder 9-41 location - Doc #400589321

[Quoted text hidden]