

FORM
6Rev
12/05State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

1771852

Date Received:

12/21/2009

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10000

Contact Name: DURONDA SMITH

Name of Operator: BP AMERICA PRODUCTION COMPANY

Phone: (970) 247-6800

Address: PO BOX 3092

Fax: (970) 247-6825

City: HOUSTON State: TX Zip: 77253

Email:

For "Intent" 24 hour notice required,

Name: Tel:

COGCC contact:

Email:

API Number 05-083-05164-00

Well Name: A.R. DAVIS

Well Number: 1

Location: QtrQtr: NENW Section: 27 Township: 35N Range: 20W Meridian: N

County: MONTEZUMA

Federal, Indian or State Lease Number:

Field Name: FLODINE PARK

Field Number: 24055

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: Longitude:

GPS Data:

Date of Measurement: PDOP Reading: GPS Instrument Operator's Name:

Reason for Abandonment: ☐ Dry ☐ Production for Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
ISMAY	5750	5857		NONE	

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF		9+5/8	32	276	100	276		
1ST		4+1/2	9.5	5,857	550			

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5701 with 14 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>12</u> sks cmt from <u>4860</u> ft. to <u>4700</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>29</u> sks cmt from <u>3091</u> ft. to <u>2767</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>12</u> sks cmt from <u>2189</u> ft. to <u>2034</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>12</u> sks cmt from <u>1106</u> ft. to <u>951</u> ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set _____ sks cmt from _____ ft. to _____ ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at 2140 ft. with 12 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 2090 ft. with 12 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 326 ft. with 113 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☒ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Plugging Date: 12/05/2009

*Wireline Contractor: A-PLUS WELL SERVICE

*Cementing Contractor: A-PLUS WELL SERVICE

Type of Cement and Additives Used: CLASS B

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

*ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: Y

Print Name: WILLIAM F. CLARK

Title: PRESIDENT A-PLUS WELL SER

Date: 12/18/2009

Email: BILL@APLUSWELL.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: 7/5/2012

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

--	--

Total Attach: 0 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)