



DISON ON WELL CEMENTING
Single Cement Surface Pipe

Customer
Well Name

EXCELL SERVICES LLC
LIPPERT 24-01-1S-45W

INVOICE #
LOCATION
FOREMAN
Date

15013
YUMA
AARON CARRASCO
8/1/2014

Treatment Report Page 2

DESCRIPTION OF JOB EVENTS

	9:20pm	Displace 1			Displace 2			Displace 3			Displace 4			Displace 5		
		BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI	BBLS	Time	PSI
Safety Meeting	9:20pm															
MIRU	6:30PM															
CIRCULATE	9:23pm	0	9:38pm	20	0			0			0			0		
Drop Plug		10	9:41pm	100	10			10			10			10		
9:38pm		16.8	9:44pm	150	20			20			20			20		
		30			30			30			30			30		
		40			40			40			40			40		
M & P		50			50			50			50			50		
Time	Sacks	60			60			60			60			60		
9:27pm	230	70			70			70			70			70		
		80			80			80			80			80		
		90			90			90			90			90		
		100			100			100			100			100		
		110			110			110			110			110		
% Excess	91%	120			120			120			120			120		
Mixed bbls	23	130			130			130			130			130		
Total Sacks	230	140			140			140			140			140		
bbl Returns	17	150			150			150			150			150		
Water Temp	65 F															

Notes:

TD @ (463) FT

SET @ (457) FT

7 INCH CASING = 20 LBS/ FT

40 FT SHOE

CEMENT TYPE = 50/50 POZ 3% CCA = MIXED & PUMPED (230 sks) .25% flo- cel

15.2 LBS/GAL= 1.07 YIELD = 4.20 GAL/ SKS

DISPLACED = (16.8)

BBLS O PIT = (17)

X

Work Performed

X *Drilling Foreman*
Title

X

Date

8-1-14