

STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

KPK Church 7A 31-2, API #005-06425, Insp Doc #673706505

1 message

Axelson - DNR, John <john.axelson@state.co.us>

Fri, Sep 26, 2014 at 7:26 AM

To: Susana Lara-Mesa <slaramesa@kpk.com>

Cc: Susan Sherman - DNR <susan.sherman@state.co.us>, OGCC EnviroScan - DNR
<OGCC.EnviroScan@state.co.us>

Hi Susi,

If the stockpile of oily waste located on location was the result of a reportable release, immediately submit an eForm 19 to document. If it was not the result of a reportable spill, please reply to me with the source of the material, date of origin and total volume.

Either way, please submit a Form 27 documenting appropriate disposal in accordance with Rule 907.e. Provide disposal manifests and total volume per Rule 907.b. Please have all of the other localized oily soil documented in the inspection cleaned up and disposed at the same time.

Please remit the Form 27 with the disposal documentation no later than October 31, 2014. Give me a call with any questions.

Thank you,
John

John E. Axelson, P.G.
East Environmental Supervisor



P 303.894.2100 x5115 | F 303.894.2109 | C 303-916-0527

1120 Lincoln Street, Suite 801, Denver, CO 80203

john.axelson@state.co.us | www.colorado.gov/cogcc

Cc. Well File API #005-06425 - Correspondence

**KPK Church insp_673706505.pdf**

124K