

**From:** [Craig Burger - DNR](#)  
**To:** ["Jennifer Lind"](#)  
**Subject:** RE: McLin A 34C-12-06-92 CBL Delay Request  
**Date:** Tuesday, October 21, 2014 7:52:00 AM

Cogcc Doc # 2597106

Jennifer,  
Ursa can defer the CBL on this well.

Craig Burger  
Northwest Area Engineer



P 970.625.2497 Ext.2 | F 970.625.5682 | C 970-319-4194  
796 Megan Ave., Suite 201, Rifle, CO 81650  
[craig\\_burger@state.co.us](mailto:craig_burger@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

---

**From:** Jennifer Lind [mailto:[jlind@ursaresources.com](mailto:jlind@ursaresources.com)]  
**Sent:** Monday, October 20, 2014 3:28 PM  
**To:** Craig Burger - DNR  
**Subject:** FW: McLin A 34C-12-06-92 CBL Delay Request

Craig, same as previous request.

Thank you,  
Jennifer

---

**From:** Jennifer Lind  
**Sent:** Monday, October 20, 2014 9:15 AM  
**To:** 'Krabacher - DNR, Jay'  
**Subject:** McLin A 34C-12-06-92 CBL Delay Request

Jay,

Ursa Operating Company, LLC is requesting a CBL deferment on the McLin A 34C-12-06-92 described below. A temperature survey was run following cementing the 4-1/2" production casing on the subject well and is attached.

Pad: McLin A  
Well: McLin A 34C-12-06-92  
API No.: 05-045-20340  
Permit No.: 400561811

Location: SE/SW, Section 12, T6S, R92W of the 6<sup>th</sup> PM  
Surface Casing: 8-5/8" set and @ 1020' with 265 sacks  
Production Casing: 4-1/2" set and cemented @ 7165' with 965 sacks  
Date Cemented: 10/8/14  
TOC from survey: 1,000'  
Top of Gas: 4,703'  
Temp Survey Run date: 10/8/14  
Volume to fill annulus: 0 Bbls  
72 hour Bradenhead Pressure Monitoring Results: 0 psig

Updated Bradenhead Pressure, if changed from 72 hour reading: 0 psig

After deferment of the CBL is approved, Ursa will continue to monitor the Bradenhead pressure until the CBL is run and notify if pressure exceeds 150 psig.

#### Bradenhead Monitoring

Duration	BHP	Time	Date	Annular Fluid Bbls
6 hours	0	20:40	10/8/14	0
12 hours	0	02:40	10/9/14	0
24 hours	0	14:40	10/9/14	0
48 hours	0	14:40	10/10/14	0
72 hours	0	14:40	10/11/14	0

A Form 4 Sundry has been submitted with the temp log .pdf and .las files (Doc # 400711575).

Jennifer Lind

Regulatory Analyst – Rockies

Ursa Operating Company, LLC

1050 17<sup>th</sup> St., Suite 2400

Denver, CO 80265

Office: 720-508-8362

Cell: 303-406-1117

[jlind@ursaresources.com](mailto:jlind@ursaresources.com)

