

From: [Craig Burger - DNR](#)
To: ["Jennifer Lind"](#)
Subject: RE: McLin A 34D-12-06-92 CBL Delay Request
Date: Tuesday, October 21, 2014 7:51:00 AM

Cogcc Doc # 2597105

Jennifer,
Ursa can defer the CBL on this well.

Craig Burger
Northwest Area Engineer



P 970.625.2497 Ext.2 | F 970.625.5682 | C 970-319-4194
796 Megan Ave., Suite 201, Rifle, CO 81650
craig.burger@state.co.us | www.colorado.gov/cogcc

From: Jennifer Lind [mailto:jlind@ursaresources.com]
Sent: Monday, October 20, 2014 3:28 PM
To: Craig Burger - DNR
Subject: FW: McLin A 34D-12-06-92 CBL Delay Request

Craig, it appears that Jay is out. He had forwarded the request to Mark Weems who also appears to be out. Would you please review the CBL delay request at your earliest convenience?

Thank you,
Jennifer

From: Jennifer Lind
Sent: Monday, October 20, 2014 9:07 AM
To: 'Krabacher - DNR, Jay'
Subject: McLin A 34D-12-06-92 CBL Delay Request

Jay,

Ursa Operating Company, LLC is requesting a CBL deferment on the McLin A 34D-12-06-92 described below. A temperature survey was run following cementing the 4-1/2" production casing on the subject well and is attached.

Pad: McLin A
Well: McLin A 34D-12-06-92
API No.: 05-045-20348
Permit No.: 400561821

Location: SE/SW, Section 12, T6S, R92W of the 6th PM
Surface Casing: 8-5/8" set and @ 1018' with 265 sacks
Production Casing: 4-1/2" set and cemented @ 7199' with 950 sacks
Date Cemented: 10/14/14
TOC from survey: 500'
Top of Gas: 4,819'
Temp Survey Run date: 10/14/14

Volume to fill annulus: 0 Bbls
72 hour Bradenhead Pressure Monitoring Results: 0 psig
Updated Bradenhead Pressure, if changed from 72 hour reading: 0 psig

After deferment of the CBL is approved, Ursa will continue to monitor the Bradenhead pressure until the CBL is run and notify if pressure exceeds 150 psig.

Bradenhead Monitoring

Duration	BHP	Time	Date	Annular Fluid Bbls
6 hours	0	15:35	10/14/14	0
12 hours	0	21:45	10/14/14	0
24 hours	0	09:45	10/15/14	0
48 hours	0	09:45	10/16/14	0
72 hours	0	09:45	10/17/14	0

A Form 4 Sundry has been submitted with the temp log .pdf and .las files (Doc # 400711556).

Jennifer Lind
Regulatory Analyst – Rockies
Ursa Operating Company, LLC
1050 17th St., Suite 2400
Denver, CO 80265

Office: 720-508-8362
Cell: 303-406-1117
jlind@ursaresources.com

