



STATE OF  
COLORADO

EnviroScan - DNR, OGCC <dnr\_ogcc.enviroscan@state.co.us>

DOC 2142408

---

## NFA for STATE 11-36 ~ SESE 36 5N 47W ~ API#05-125-06311 ~ Facility ID #252437 ~ Remediation #8725

1 message

---

**Eckman - DNR, Annie** <annie.eckman@state.co.us>

Tue, Nov 4, 2014 at 11:07 AM

To: Loni Davis <LDavis@augustusenergy.com>

Cc: Rob Young - DNR <rob.young@state.co.us>, "EnviroScan, OGCC" <OGCC.EnviroScan@state.co.us>, Katrina Andrus - DNR <katrina.andrus@state.co.us>

### STATE 11-36 ~ SESE 36 5N 47W ~ API#05-125-06311 ~ Facility ID #252437 ~ Remediation #8725

COGCC has received the Form 27 submitted for the partially buried tank removal at the above referenced facility. The form has been approved, and assigned Remediation #87275; a copy of the signature page indicating that the form is approved is attached.

Based on our review of this information, COGCC concurs that there is no apparent impact to soil associated with the recently removed, partially buried produced water tank, and the Remediation Project number has been closed (document #200416246). However, surface reclamation must meet the COGCC 1004 series rules for vegetative cover. Please retain a copy of this email as verification of No Further Action required.

**Ann C Eckman, PG**  
**Environmental Protection Specialist**

co\_dnr\_div\_ogcc\_300\_rgb\_ltrhd\_v3



P 303.894.2100 Ext 5124 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

[annie.eckman@state.co.us](mailto:annie.eckman@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)



**COGCC Scan (7) (1).pdf**

1205K