



STATE OF
COLORADO

EnviroScan - DNR, OGCC <dnr_ogcc.enviroscan@state.co.us>

**NFA for LUEKING 2-19 ~ SESE 19 5N 46W ~ API #05-125-06305 ~
Facility#252431 ~ Remediation Project #8718**

DOC 2142416

1 message

Eckman - DNR, Annie <annie.eckman@state.co.us>

Tue, Nov 4, 2014 at 12:26 PM

To: Loni Davis <LDavis@augustusenergy.com>

Cc: Rob Young - DNR <rob.young@state.co.us>, "EnviroScan, OGCC" <OGCC.EnviroScan@state.co.us>, Katrina Andrus - DNR <katrina.andrus@state.co.us>

LUEKING 2-19 ~ SESE 19 5N 46W ~ API #05-125-06305 ~ Facility#252431 ~ Remediation Project #8718

COGCC has received the Form 27 submitted for the partially buried tank removal at the above referenced facility. The form has been approved, and assigned Remediation #8718; a copy of the signature page indicating that the form is approved is attached.

Based on review of data presented, soils with elevated SAR, have been treated and exist below the root zone. Given this, these soils are not likely to impact future vegetation establishment and COGCC concurs that no further action is necessary at this time. However, it should be noted that this case could be re-opened in the future. Should conditions at the site indicate contaminant concentrations in surficial soils exceeding COGCC standards, or, if ground water is found to be significantly impacted, further investigation and/or remediation activities may be required at the site. Additionally, if re-vegetation is not sufficient to meet COGCC 1004 series rules, remediation of soils will be required.

The Remediation Project number has been closed (document #200416256). Please retain a copy of this email as verification of No Further Action required.

Ann C Eckman, PG
Environmental Protection Specialist

co_dnr_div_ogcc_300_rgb_ltrhd_v3



P 303.894.2100 Ext 5124 | F 303.894.2109

1120 Lincoln Street, Suite 801, Denver, CO 80203

annie.eckman@state.co.us | www.colorado.gov/cogcc



COGCC Scan (7) (1).pdf
1205K

