

**From:** [Diana Burn - DNR](#)  
**To:** ["Tim Pivonka"](#)  
**Cc:** [Cory Essex - DNR](#)  
**Subject:** Feik #5 075-06063  
**Date:** Friday, December 05, 2014 11:07:00 AM  
**Attachments:** [image001.png](#)  
[Timka Resources 88370 Delinquents.xlsx](#)

---

05-075-06063 [FEIK #5](#)  
CNESE 5 8N 54W 6 PM

Hi there - this well does not have any production reporting. It was spud in March 2007, Form 7 Monthly Report of Operations are due from the month of spud to one month after abandonment.

Please provide the production information for this well and all of the wells listed in the Delinquent Reports (attached) to bring them current by January 5, 2015.

Please consider this as a notice of the well(s) being out of compliance.

It is recommended that the corrective actions are taken seriously and that the well is brought into compliance. Non-compliance will be referred for enforcement.

This Warning Letter is to inform you that the oil and gas facility or the oil and gas operations listed above may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission ("COGCC") and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator's compliance with this Warning Letter is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **January 5, 2015(Production records brought current)**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1.

The COGCC requires Timka Resources Ltd. to implement corrective action(s) for the conditions identified below. The listed well is out of compliance with COGCC Rule 309.

**Failure to Comply with Warning Letter:**

If Timka Resources Ltd. fails to perform required corrective actions, COGCC will issue a Notice of Alleged Violation and seek penalties pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)

If you have any questions about this Warning Letter, please contact me.

Thanks,  
Diana

Diana Burn, P.E.  
Eastern Engineering Supervisor



P 303.894.2100 x5106 | F 303.894.2109 | C 303.918.6320  
1120 Lincoln Street, Suite 801, Denver, CO 80203  
[Diana.Burn@state.co.us](mailto:Diana.Burn@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)