

FORM

42

Rev  
09/12

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

Document Number:

NOTICE OF NOTIFICATION

Entity Information

OGCC Operator Number: 10470 Contact Person: William Lloyd  
Company Name: Cirque Resources LP Phone: (303) 226-9500  
Address: 475 17th St., Suite 1600 Fax: (303) 226-9595  
City: Denver State: CO Zip: 80202 Email: blloyd@cirqueresources.com

API #: 05-12339863 Facility ID: 438065 Location ID: 438066  
Facility Name: Railay 28-3-1CH  
Sec: 28 Twp: 12N Range: 66W QtrQtr: NENW Lat: N 40.98531 Long: W 104.78359

NOTICE OF HYDRAULIC FRACTURING TREATMENT – 48-hour notice required

Date of Treatment: Time: (HH:MM)

NOTICE OF SPUD – 48-hour notice required **Surface Hole Spud ONLY**

Spud Date: Time: (HH:MM)

Rig Name:

NOTICE OF CONSTRUCTION OF A NEW LOCATION OR MAJOR CHANGE – 48-hour notice required

Start Date:

NOTICE TO RUN AND CEMENT CASING – 24-hour notice

Start Date: Time: (HH:MM) String:

FORMATION INTEGRITY TEST – 24-hour notice

Test Date: Time: (HH:MM)

MECHANICAL INTEGRITY TEST – 10-DAY NOTICE

Test Date: Time: (HH:MM) Underground Injection Control(UIC) Well?

BRADENHEAD TEST – 48-hour Notice

Test Date: Time: (HH:MM)

BLOW OUT PREVENTER TEST – 24-Hour notice

Test Date: Time: (HH:MM)

SITE READY FOR RECLAMATION INSPECTION :

PIT LINER INSTALLATION – 48-hour notice

Install Date:

**SIGNIFICANT LOST CIRCULATION – Notify within 24 hours, report mud losses in excess of 100 barrels which require shutdown of operations for an hour or longer to pump lost circulation material and rebuild pit volume**

Date of Lost Circulation: \_\_\_\_\_ Time: \_\_\_\_\_ (HH:MM)  
Measure Depth: \_\_\_\_\_ (feet) Mud Volume Lost: \_\_\_\_\_ (bbl)  
Significant Kick Ensued? \_\_\_\_\_

A Form 23 (Well Control Report) is required for Significant Kicks within 15 days. A significant kick shall be defined as one that is managed by shutting in the well to circulate out the kick or that is managed by going on choke and requiring an increase in mud weight exceeding 3/10ths of one pound per gallon to control.

**NOTICE OF HIGH BRADENHEAD PRESSURE DURING STIMULATION – Notify within 24 hours when bradenhead pressure increases more than 200 psig during stimulation. This satisfies Rule 341 verbal notification requirements. Submit a follow-up Form 4 within 15 days.**

Date and time of High Bradenhead Pressure: \_\_\_\_\_ Time: \_\_\_\_\_ (HH:MM)

**OTHER – AS SPECIFIED BY PERMIT CONDITION add (2/2A)**


Describe Permit Condition: \_\_\_\_\_  
Date: \_\_\_\_\_ Time: \_\_\_\_\_ (HH:MM)

**NOTICE OF INSPECTION CORRECTIVE ACTIONS PERFORMED**

Corrective Actions required by field inspection document # 673801705 have been performed on 02/23/2015  
Site is ready for re-inspection.

This form must be signed by an authorized agent of the entity making assertion.

I certify under penalty of perjury that this report has been examined by me and to the best of my knowledge is true, correct and complete.

Print Name: William Lloyd Email: blloyd@cirqueresources.com  
Signature:  Title: Sr VP - Operations Date: 02/23/2015