


2115 117th Avenue  
Greeley, CO 80634

Tel: 970.304.5000  
Fax: 970.304.5099  
www.nobleenergyinc.com



Land Department

February 10, 2015

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Article #7013 0600 0000 9396 0325

John D. Larson  
31256 County Road 59  
Gill, Colorado 80624

Re: **PFEIFFER 16-26**  
Request for Approval to Re-Enter and Re-Plug  
Township 6N, Range 64W  
Section 26: SE/4SE/4  
Weld County, CO

Dear Mr. Larson:

On June 20, 2013, the Colorado Oil and Gas Conservation Commission (COGCC) enacted a new policy requiring that all operators of horizontal wells completed in the Niobrara Shale formation (the "Formation") to review the completion records for any well that penetrated the Formation that is located within fifteen hundred feet (1,500') of the anticipated bore hole of any such horizontal well.

In accordance with this COGCC policy Noble has evaluated the above captioned well(s) and has determined that it is necessary to re-enter and re-plug the well(s) in order to be adequately isolated from horizontal wells.

As such, Noble requests that you, the surface owner of the lands described above, grant Noble permission to re-enter and re-plug the well, subject to \$500 entry fee and \$1500 per acre damage reimbursement for growing wheat crop. Damage and entry fee shall not be less than \$2,000. (JL)

Thank you for your cooperation in this matter. If you have any questions or concerns, please feel free to contact me at the numbers listed on the enclosed business card.

Sincerely,

**NOBLE ENERGY, INC.**

By:   
Cory Neighbors

**OWNER: JOHN D. LARSON**

By:   
John D. Larson