



March 16, 2015

Mr. Matt Lepore  
Colorado Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801  
Denver, CO 80203

**Re: Request for Rule 317.p Exception (Open-Hole Logging Requirements)**  
Regnier Farms 1A-1L 19H-B268  
NWNE Sec 19 T2N R68 Weld County, CO

Dear Mr. Lepore:

Please let this letter serve as a request for a Rule 317.p Exception for the proposed wells listed above. Rule 317.p requires logging all wells with a minimum of a resistivity log with gamma ray to adequately describe the stratigraphy and open-hole logs to adequately verify the setting depth of surface casing and aquifer coverage.

Encana is requesting to run a combination RST/CBL (reservoir saturation tool) cased hole log on the 7" casing on Regnier Farms 1D-19H-B268, one of the first wells to be drilled on the pad, from approximately 500' to 6500' MD.

All of the captioned wells will have a cement bond log with gamma ray run from the intermediate casing shoe, or as close as possible, to above surface casing shoe to verify the setting depth of surface casing and aquifer coverage.

The horizontal portion of all subject wells will be logged while drilling with a gamma ray tool.

Encana will report and submit all logs run on the Form 5 for every well and report that alternative logs were run per Rule 317.p and identifying the well that was run with the alternative logs.

Thank you for your assistance with this matter. If you have any questions or comments, please contact me at 720-876-5845

Sincerely,

**ENCANA OIL & GAS (USA) INC.**

A handwritten signature in black ink that reads "Toby Sachen". The signature is written in a cursive, flowing style.

Toby Sachen  
Regulatory Analyst

**Encana Oil & Gas (USA) Inc.**  
Republic Plaza  
370 – 17 Street, Suite 1700  
Denver, Colorado  
United States 80202  
t 303.623.2300  
f 303.623.2400  
[www.encana.com](http://www.encana.com)