

Federal 8-7

Inspection# 675201349

Wellhead has no production equipment attached. Well should have TA status.



Stored equipment/ debris on location.



Pipe going from wellhead to
blowdown pit.



Blowdown pit.

