

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400837141

Date Received:

05/07/2015

Spill report taken by:

Spencer, Stan

Spill/Release Point ID:

441351

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC	Operator No: 96850	Phone Numbers
Address: 1001 17TH STREET - SUITE #1200		Phone: (970) 6832295
City: DENVER State: CO Zip: 80202		Mobile: (970) 5890743
Contact Person: Karolina Blaney		Email: karolina.blaney@wpxenergy.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400815902

Initial Report Date: 03/26/2015 Date of Discovery: 03/26/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNW SEC 27 TWP 6S RNG 94W MERIDIAN 6

Latitude: 39.501040 Longitude: -107.882523

Municipality (if within municipal boundaries): County: GARFIELD

Reference Location:

Facility Type: WELL PAD Facility/Location ID No 324122
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: warm, sunny

Surface Owner: FEE Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

The release was caused by corrosion of the produced water tank. Estimated 10 bbls of produced water leaked out of the tank into the dirt SPCC containment, saturated through a portion of the berm, and migrated 10' to the southwest of the SPCC containment. Though the spill reached a rill on the edge of the pad, it did not leave the footprint of the pad surface, so was contained on location.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
3/26/2015	COGCC	Stan Spencer	970-987-2497	Initial Form 19
3/26/2015	County	Kirby Wynn	970-625-5905	Email
3/26/2015	Fire Department	Orrin Moon	970-625-1243	Email
3/26/2015	Surface owner		-	Phone call

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Karolina Blaney

Title: Environmental Specialist Date: 05/07/2015 Email: karolina.blaney@wpenergy.com

COA Type

Description

<u>COA Type</u>	<u>Description</u>

Attachment Check List

Att Doc Num

Name

400837141	FORM 19 SUBMITTED
400837142	ANALYTICAL RESULTS

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

Agency	Based on review of information presented, it appears that no further action is necessary at this time, and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be significantly impacted, then further investigation and/or remediation activities may be required at the site. Ensure that dirt berm is either adequately compacted or lined to prevent saturation or leakage. Berms must be impermeable.	5/18/2015 3:21:09 PM
--------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------

Total: 1 comment(s)