




05-103-06189  
Location # 397183

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979) 5-88-BCB-#2

To: District Engineer BLM, Fluid Minerals Branch, P.O. Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_
- 2. BBLS Discharged: 3 bbls. oil 25 prod. wtr. BBLS Lost: 0 oil - 15 prod. water
- 3. Contained on location: Yes X No \_\_\_\_\_
- 4. Date and time of event: 5-18-88 8:00 AM
- 5. Date and time reported to BLM N/A
- 6. Location of event: NE/SW Sec 25 T2N R102W
- 7. Specific nature and cause of event  
Ground setting and broke fiberglass joint.
- 8. Describe resultant damage:  
N/A
- 9. Time required for control of event: 15 mins.
- 10. Action taken to control and contain:  
Bleed bulk line. Washed oil in siphon pond and collected. 15 bbls. water soaked into ground.
- 11. Action taken to prevent recurrence:  
Line repaired
- 12. Cause of death:  
N/A
- 13. Other agencies notified:  
Colorado Department of Health, Air Quality Control, Denver, Co.  
Colorado Oil and Gas Conservation Commission, Denver, Co.-Written Report only
- 14. Other pertinent information:



Signature T. L. Hurst Date 5/27/88  
T.L. Hurst  
Title Unit Area Supervisor