




02469043

05705-06227  
Location # 314618REPORT OF UNDESIRABLE EVENT  
NTL-3A (EFFECTIVE MARCH 1, 1979)To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_
2. BBLS Discharged: 1800 bbls Inj Water BBLS Lost: 600 bbls
3. Contained on location: Yes X No \_\_\_\_\_
4. Date and time of event: 6/9/87 12:15 A.M.
5. Date and time reported to BLM: 6/10/87 11:00 Mary Branscom
6. Location of event: 100 yd SW of Fee 57 (SESE Sec 28, T2N, R102W)  
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

Leak in 6" lateral line.

8. Describe resultant damage:

Water ran  $\frac{1}{4}$  mile across flat and down small wash and gathered at road by Fee 135X.

9. Time required for control of event:  $\pm$  1 hr
10. Action taken to control and contain:  
Sucked up water and hauled to Fee 10 pit.  $\pm$  600 bbls soaked into ground.
11. Action taken to prevent recurrence:-  
Replace section of line.
12. Cause of death:  
N/A
13. Other agencies notified:  
8:24 A.M.  
COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO - John Chase 6/10/87  
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 6/10/87
14. Other pertinent information:

Signature

T.L. Hurst

Date

6/13/87

Title Area Supervisor

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.