




02469036

09-103-07173
location # 314763



REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
- 2. BBLS Discharged: 50 BBLS Lost: 0
- 3. Contained on location: Yes No _____
- 4. Date and time of event: 09/16/87 5:00 P.M.
- 5. Date and time reported to BLM: N/A
- 6. Location of event: 50 yds. W. of M.B. Larsen 11X25, SW SW 25 T2N 102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
- 7. Specific nature and cause of event

Leak in main inj. line.

- 8. Describe resultant damage:
- 9. Time required for control of event: Approximately 20 minutes
- 10. Action taken to control and contain:

Shut off main valve, water went into syphon pit.

- 11. Action taken to prevent recurrence:-
Repaired line

- 12. Cause of death:

N/A

- 13. Other agencies notified:

~~_____~~
COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO -
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

- 14. Other pertinent information:

Signature Wayne K Larsen Date 9-24-87

Title AREA SUPERVISOR