



## REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)

05-103-09145  
Location # 315736

9/87-BCB-#3

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626  
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill ☒ Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_

2. BBLS Discharged: 7 bbls water, 2 bbls oil BBLS Lost: -0-

3. Contained on location: Yes ☒ No \_\_\_\_\_

4. Date and time of event: 9/17/87 9:30 A.M.

5. Date and time reported to BLM: N/A

6. Location of event: SW SW 24 T2N 103W, Lacy 12Y  
Rangely Weber Sand Unit, Rio Blanco County, Colorado

7. Specific nature and cause of event

3" gate valve failed on wellhead.

8. Describe resultant damage:

9. Time required for control of event: 20 mins.

10. Action taken to control and contain:

11. Action taken to prevent recurrence:-

12. Cause of death:

N/A

13. Other agencies notified:

COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO -  
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

14. Other pertinent information:

Signature Wayne K. Lauer Date 9-24-87Title AREA SUPERVISOR

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.

