



REPORT OF UNDESIRABLE EVENT
NTL-3A (EFFECTIVE MARCH 1, 1979)

103-08298

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201
Location # 315322

- 1. Spill Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
- 2. BBLS Discharged: 90 bbls water BBLS Lost: 90 bbls water
- 3. Contained on location: Yes No _____
- 4. Date and time of event: 1-26-87 12:00 noon
- 5. Date and time reported to BLM: Not required
- 6. Location of event: 50 yds S of A. C. MCLAUGHLIN 75X SE SW Sec. 13 T2N R 102W
Rangely Weber Sand Unit, Rio Blanco County, Colorado
- 7. Specific nature and cause of event

Water Injection Line leak

- 8. Describe resultant damage:
- 9. Time required for control of event: 15 minutes

10. Action taken to control and contain:

Shut in source, repaired 3" line and returned to injection.

11. Action taken to prevent recurrence:-

Repaired line.

12. Cause of death:

N/A

13. Other agencies notified:

[Redacted]
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO -
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

14. Other pertinent information:

Signature T. L. Hurst *T. L. Hurst* Date 2/4/87

Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.