

1/ 28

BL. BARRINGTON - MEMPHIS TENN TO 53'
NW OF KPK WELL. HE EXPECTS HENDERSON TO
SEND IN WELLS TODAY RESUMING DR

21

~~DR~~ Henderson did much agreement to [unclear]

on 6065, Rasmussen 42-28 shows as AL

1/4/08

303 486 9166 - Sandy Henderson

Talked to Dan Bales, Blake Bretton LL
have pumpjack (KPK) in alfalfa field. want to put
well ~400ft south of KPK well.

Fields too far from KPK.

They want to increase tank size at battery. want
from small to bigger one 8' high to 12' wide.
meta remember and operator.

Carrie Byers → Encana Supervisor sized new
tank would be big enough - for all future use
would lose 120 bales of alfalfa per year if road
is as proposed

elect. on left side south of KPK well
if 100ft south would be ok
can't plant alfalfa - alfalfa. must plant oats
or other crop in between. Get much less crop yield
with oats than ~~alfalfa~~ alfalfa

Paper given to landowner

changed well/section from S-8?


(720) 876 5716 → Blake Bretton
msg to call

1/10/07 B. Bretton. Don't want to be too close to KPK well as it is old
and questionable well integrity. Also, drilling near exist. Rasmussen may
warrant indemnity.

1/10/07 → Per D. Abstrom, Encana needs water for sup. want to
drill >50ft from existing well head on hearing.

1/10/07 - Inform Bretton, Abstrom ops. He'll discuss & can be
1) Provide 48 hour notice of MIRU to John Duran at 719-846-4715 2) Tag all cement plugs to verify that cement plugs stay in
place

**Colorado Oil and Gas Conservaton Commission (COGCC)
Onsite Inspection Request Form
(Effective for APDs submitted after February 15, 2005)**



As the surface owner(s) where a proposed well is being drilled, I/we are requesting that the COGCC conduct an onsite inspection. I/we did not execute a lease nor did I/we execute a surface use or other relevant agreement for the proposed well. I/we understand that good faith consultation with the operator as required under COGCC Rule 306. is required to have occurred prior to making this request to the COGCC to conduct an onsite inspection, and that this onsite inspection request must be received by the COGCC within ten (10) business days of the first day of the Rule 306. consultation.

Surface Owner Contact Information:

Name: Sandy Henderson
Address: 8027 Morning side Dr
Telephone No. 303-485-9466
Cell Phone No. 303-909-3619

Well Operator and Location Information:

Operator: Encana
Well Name: Rasmussen 42-28 Well
Location: Section 28: SE/4NE/4 Township 2 North, Range 68 West
Quarter/Quarter Section Township Range
County: Weld County, Colo

First date Rule 306. consultation occurred: Jan 3, 2008
Date

Proposed two (2) dates for the COGCC onsite consultation (must be within thirty (30) days of the request)

1st date Jan 23, '08 2nd date Jan 24, '08

I would prefer to have a representative of the appropriate Local Government (COGCC Local Governmental Designee) invited to attend the onsite inspection? yes ___ no

Briefly describe the unresolved issues related to the proposed well (The onsite inspection shall not address matters of surface owner compensation, property value diminution, future use of the property or any private party contractual issues between the operator and the surface owner.)

Well site location, battery size, travel path to site
unreasonable crop loss

Signature(s) Sandy Henderson Date Jan 4, 2008

Please fax or first class mail this request for an onsite inspection to:

Colorado Oil and Gas Conservation Commission
Attn: Permit Supervisor
1120 Lincoln Street Suite 801
Denver, CO 80203
FAX (303) 894-2109

FAXED 1/4/08
MAILED 1/4/08

**Colorado Oil and Gas Conservation Commission (COGCC)
Onsite Inspection Request Form
(Effective for APDs submitted after February 15, 2005)**

As the surface owner(s) where a proposed well is being drilled, I/we are requesting that the COGCC conduct an onsite inspection. I/we did not execute a lease nor did I/we execute a surface use or other relevant agreement for the proposed well. I/we understand that good faith consultation with the operator as required under COGCC Rule 306. is required to have occurred prior to making this request to the COGCC to conduct an onsite inspection, and that this onsite inspection request must be received by the COGCC within ten (10) business days of the first day of the Rule 306. consultation.

Surface Owner Contact Information:

→ Name: Sandy Henderson
Address: 8027 Morningside Dr
Telephone No. 303-485-9466
Cell Phone No. 303-909-3619

Well Operator and Location Information:

Operator: Enkana
Well Name: Rasmussen 42-28 Well
Location: Section 28: SE/4NE/4 Township 2 North, Range 68 West
Quarter/Quarter Section Township Range
County: Weld County, Colo

First date Rule 306. consultation occurred: Jan 3 2008
Date

Proposed two (2) dates for the COGCC onsite consultation (must be within thirty (30) days of the request)

1st date Jan 23 '08 2nd date Jan 24, '08

I would prefer to have a representative of the appropriate Local Government (COGCC Local Governmental Designee) invited to attend the onsite inspection? yes ___ no

Briefly describe the unresolved issues related to the proposed well (The onsite inspection shall not address matters of surface owner compensation, property value diminution, future use of the property or any private party contractual issues between the operator and the surface owner.)

Well site location, battery size, travel path to site
unreasonable crop loss


Signature(s) Sandy Henderson Date Jan 4, 2008


Please fax or first class mail this request for an onsite inspection to:

Colorado Oil and Gas Conservation Commission
Attn: Permit Supervisor
1120 Lincoln Street Suite 801
Denver, CO 80203
FAX (303) 894-2109

112273
Leat: 40. H2015
Lon: -105. 00144
Op: 10065

FAxed 1/4/08





RASMUSSEN C UNIT 2

HINGLEY 2

RASMUSSEN 42-28

28

27