




02470172

OS-103-05545
LOC# 3/2/395

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)

3-87-BCB-5



To: District Manager, B.L.M., Fluid Minerals, P.O. Box 248, Craig, Colorado 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLs Discharged: 300 bbls BBLs Lost: 50 bbls
3. Contained on location: Yes No _____
4. Date and time of event: 3/22/87 4:00 P.M.
5. Date and time reported to B.L.M.: 3/23/87 9:47 A.M. (Mary Branscom)
6. Location of event: C.S. 13 NE SE Sec 25, T2N, R103W
7. Specific nature and cause of event
Electrical problems with water pump. Pit was already high because of mechanics work.
8. Describe resultant damage:
Side of pit washed out
9. Time required for control of event: ± 30 Min.
10. Action taken to control and contain:
Hole in pit was plugged. #2 water pump started. Bar ditch was diked and excess water was sucked up with vacuum truck.
11. Action taken to prevent recurrence:
Pit side will be rebuilt and tamped.
12. Cause of death:
N/A
- *13. Other agencies notified:
Colorado Dept. of Health, WTR Quality Control, Denver, Colorado
Colorado Oil & Gas Conservation Comm, Denver, Colorado (Written Reprot Only)
14. Other pertinent information:

Signature T.L. Hurst Date 4/2/87
T.L. Hurst

Title Area Supervisor

* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.