




02470160

DS-103-08672

Loc# 315537

REPORT OF UNDESIRABLE EVENT



NTL-3A (EFFECTIVE MARCH 1, 1979)

COLO. OIL & GAS CONS. COMM.

To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

- 1. Spill [X] Discharge \_\_\_\_\_ Blowout \_\_\_\_\_ Accident \_\_\_\_\_ Fire or Explosion \_\_\_\_\_
2. BBLS Discharged: 50 bbls water BBLS Lost: 5 bbls
3. Contained on location: Yes [X] No \_\_\_\_\_
4. Date and time of event: 2/3/87 11:00 am
5. Date and time reported to BLM: Not Required
6. Location of event: Low Pressure Water Inj. Line NE SW, Sec 3, R102W, T1N Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event

Corrosion in Weld

- 8. Describe resultant damage:
N/A
9. Time required for control of event: +/- 15 min

- 10. Action taken to control and contain:
Closed in valve at water plant. Sucked up water on surface.

- 11. Action taken to prevent recurrence:-
Replaced 45° angle pipe.

- 12. Cause of death:
N/A

- 13. Other agencies notified:
COLO. DEPT. OF HEALTH, WTR QUALITY CONTROL, DENVER, CO -
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only

- 14. Other pertinent information:

Signature T.L. Hurst Date 2/5/87
T. L. Hurst, Area Supervisor

Title

\*\* A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.