




02470158

CS-103-08498

Loc# 315439

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)



To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 1000 Inj Water BBLS Lost: 1000
3. Contained on location: Yes _____ No X
4. Date and time of event: 6/5/87 2:00 A.M.
5. Date and time reported to BLM: 6/10/87 11:00 A.M. Mary Branscom
6. Location of event: High Press Inj Line DRA-S (SESE Sec 32, T2N, R102W)
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event
Pipe failure.
8. Describe resultant damage:
± 800 bbls reached Stinking Water Creek which was dry. All water soaked into ground.
9. Time required for control of event: ± 15 minutes
10. Action taken to control and contain:
Lateral valve shutoff.
11. Action taken to prevent recurrence:-
Replace section of pipe.
12. Cause of death:
N/A
13. Other agencies notified:
COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO - Bud Mahn 6/5/87 4:00 P.M.
COLO. OIL & GAS CONSV COMM, DENVER, CO - Written Report Only 6/10/87
14. Other pertinent information:

Signature T.L. Hurst Date 6/13/87
T.L. Hurst
Title Area Supervisor

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.