




02470157
05-103-61029
Loc # 314242

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)



To: District Engineer BLM, Fluid Minerals Branch, P O Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____
2. BBLS Discharged: 1000 - bbls inj water BBLS Lost: 1000
3. Contained on location: Yes _____ No X
4. Date and time of event: 6/3/87 8:00 p.m.
5. Date and time reported to BLM: 6/10/87 11:00 a.m. Mary Branscom
6. Location of event: U.P. 15-21, NENW Sec 28, R102W, T2N
Rangely Weber Sand Unit, Rio Blanco County, Colorado
7. Specific nature and cause of event
Leak in fitting on DRA Inj Line.
8. Describe resultant damage:
±800 bbls reached Stinking Water Creek, which was dry. All water soaked into ground
9. Time required for control of event: ± 45 minutes
10. Action taken to control and contain:
Shut line in.
11. Action taken to prevent recurrence:-
Old fitting removed and stub line capped.
12. Cause of death:
N/A
13. Other agencies notified:
COLO. DEPT. OF HEALTH, AIR QUALITY CONTROL, DENVER, CO - Bud Mahn 4:00 p.m.
COLO. OIL & GAS CONSV COMM, DENVER, CO - Called & Written 6/5/87
Written Report Only 6/10/87
14. Other pertinent information:

Signature _____

T.L. Hurst
T.L. Hurst, Area Supervisor

Date _____

6/13/87

Title _____

** A COPY OF THIS FORM WAS MAILED TO EACH AGENCY LISTED IN PARAGRAPH 13 ABOVE.