




02470342

operator # 16700

REPORT OF UNDESIRABLE EVENT

NTL-3A (EFFECTIVE MARCH 1, 1979)



To: District Engineer BLM, Bureau of Land Management, P. O. Box 248, Craig, CO 81626
From: Chevron U.S.A. Inc., P. O. Box 599, Denver, Colorado 80201

1. Spill X Discharge _____ Blowout _____ Accident _____ Fire or Explosion _____2. BBLS Discharged: 100 bbls. inj. water BBLS Lost: 100 bbls.3. Contained on location: Yes X No _____4. Date and time of event: 10/31/87 3:00 A.M.5. Date and time reported to U.S.G.S.: 11/02/876. Location of event: SE NW Sec 2, R102W, T1N

7. Specific nature and cause of event

Line failure in weld of 45° fitting.

8. Describe resultant damage:

N/A

9. Time required for control of event: ± 15 min.

10. Action taken to control and contain:

Valve closed. All water soaked into ground.

11. Action taken to prevent recurrence:

Replaced fitting and section of pipe.

12. Cause of death:

N/A

13. Other agencies notified:

Colorado Department of Health, Air Quality Control, Denver, Co.
Colorado Oil and Gas Conservation Commission, Denver, Co - Written Report Only

14. Other pertinent information:

Signature

T. L. Hurst

Date

Title