

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400870238

Date Received:

07/17/2015

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

442543

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>WHITING OIL & GAS CORPORATION</u>	Operator No: <u>96155</u>	Phone Numbers
Address: <u>1700 BROADWAY STE 2300</u>		Phone: <u>(432) 264-0004</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(432) 238-9767</u>
Zip: <u>80290</u>		Email: <u>robert.deotte@whiting.com</u>
Contact Person: <u>Robert DeOtte</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400870238

Initial Report Date: 07/17/2015 Date of Discovery: 07/16/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWNE SEC 11 TWP 10n RNG 58w MERIDIAN 6Latitude: 40.854164 Longitude: -103.832767Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 436611☐ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0Specify: 14.5 bbls of oil released inside berm

Land Use:

Current Land Use: NON-CROP LANDOther(Specify): RangelandWeather Condition: SunnySurface Owner: FEEOther(Specify): Timbro Ranch and Cattle Co

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

14.5 bbls of oil was released due to a stuck dump valve on a separator causing a tank to overflow. Liquid was contained inside secondary containment. Free liquid was recovered with a vacuum truck and impacted soils were excavated and placed on a plastic liner for onsite treatment.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
7/17/2015	Landowner	Timbro Ranch & Cattle Co	970-396-5885	Notified

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Robert DeOtte

Title: Env. Coord. Date: 07/17/2015 Email: robert.deotte@whiting.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400870238	FORM 19 SUBMITTED
-----------	-------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)