

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400888651

Date Received:

08/25/2015

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC	Operator No: 10112	Phone Numbers
Address: 16000 DALLAS PARKWAY #875		Phone: (918) 526-5592
City: DALLAS State: TX Zip: 75248-6607		Mobile: (918) 638-1153
Contact Person: Rachel Grant		Email: regulatory@foundationenergy.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400888651

Initial Report Date: 08/24/2015 Date of Discovery: 08/20/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENE SEC 6 TWP 7N RNG 60W MERIDIAN 6

Latitude: 40.609950 Longitude: -104.128111

Municipality (if within municipal boundaries): County: WELD

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No
 No Existing Facility or Location ID No.
 Well API No. (Only if the reference facility is well) 05-123-20169

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >0 and <1 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Approximately 1 bbl oil, 9 bbls produced water released inside berms

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: dry

Surface Owner: FEE Other(Specify): Robert E Hill

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area
As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Due to a malfunction in the treater, the water tank overflowed, spilling approximately 10 barrels (1 bbl oil, 9 bbls water) inside the berms on location. A vac-truck was dispatched immediately and sucked up the free-standing fluid.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
8/20/2015	COGCC	Rick Allison	970-461-2970	Email to notify of release, call on 8/21
8/20/2015	Landowner	Robert Hill	970-656-3648	Called to notify of release, already aware
8/24/2015	Weld County LEPC	Roy Rudisill	970-304-6540	Email to notify of release

OPERATOR COMMENTS:

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Rachel Grant

Title: Sr. HSE/Regulatory Tech. Date: 08/25/2015 Email: regulatory@foundationenergy.com

Attachment Check List

Att Doc Num **Name**

--	--

Total Attach: 0 Files

General Comments

User Group **Comment** **Comment Date**

--	--	--

Total: 0 comment(s)