

**Response to COGCC Field Inspection Report (Document #673502754)**  
**Greasewood 4-8H**

Bill Barrett Corporation (BBC) has or will complete the following actions by October 30, 2015. As noted below, depending on weather conditions, seeding of the location and pipeline may not occur by October 30, 2015 but will occur during the late fall of 2015.

**Greasewood 4-8H Location**

The well on this pad was recently re-frac'd and work related to interim reclamation had started prior to the COGCC field inspection. Materials and equipment related to the re-frac were in the process of being removed and flow-back equipment rearranged on the location to facilitate interim reclamation. Dirt work on the location commenced the morning of September 2, 2015 and will be completed by approximately September 21, 2015. Seeding of the location with an appropriate seed mix will take place as late in the fall of 2015 as possible but, pending weather conditions, should be completed by October 30, 2015. Photographs of the work in progress as of September 17, 2015 are attached.

**Pipeline**

This pipeline right-of-way (ROW), both on and off of the complainant's property, was reseeded in the fall of 2013. In comparing the portions of the ROW that are not on the complainant's property have significantly more vegetation than on the complainant's property and BBC believes that the fact that the complainant's cattle appear to move along the fence line adjacent to the pipeline is one of the primary reasons that the vegetation has not established as successfully as desired. The actions that BBC will take include over seeding the ROW on the complainant's property by hand raking and broadcast seeding; continued weed control; and, pending landowner approval, constructing a temporary fence on the south side of the ROW to prevent the cattle from entering the ROW until vegetation has been successfully re-established. As noted for the oil and gas location, seeding will be completed as late in the fall as possible to increase the chances for success.



Entrance to Greasewood 4-8H location looking north – September 17, 2015



Greasewood 4-8H location looking north-northwest – September 17, 2015



Greasewood 4-8H location looking north-northeast - September 17, 2015



Greasewood 4-8H location looking west – September 17, 2015