



Kerr-McGee Oil & Gas Onshore LP

A subsidiary of Anadarko Petroleum Corporation

1099 18th Street
Denver, CO 80202
720-929-6000

October 12, 2015

Matt Lepore
Director, Colorado Oil and Gas Conservation Commission
Department of Natural Resources
The Chancery Building
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: **30 Day Certification Letter - 318A.e**
PUMA FED 34N-35HZ (Doc # 400894395)
Township 1 North, Range 67 West
Section 23: SWSW
Unit Acreage: 720
Unit Spacing: SEC 22: SESE; SEC 23: SWSW; SEC 26: W2W2; SEC 27: E2E2; SEC 34:
E2E2; SEC 35: W2W2
Weld County, Colorado

Dear Mr. Lepore:

Kerr-McGee Oil and Gas Onshore LP (“KMG”) hereby certifies that a thirty (30) day notice has been given by certified mail to all mineral owners in the proposed wellbore spacing unit. We have not received any objections to such well location, proposed spacing unit, or additional producing formation. KMG hereby respectfully requests approval of this boundary well.

If you have any questions or issues regarding this permit, please contact Cheryl Light at (720) 929-6461.


Very truly yours,

Kerr-McGee Oil and Gas Onshore LP

A blue ink signature of Craig Richardson.

Craig Richardson
Regulatory Analyst II

Enclosure




CERTIFICATE OF SURVEYOR:

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY PLAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.S. 38-51-102 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

Benjamin J. Reenders
PROFESSIONAL LAND SURVEYOR
 38305

BENJAMIN J. REENDERS
 PROFESSIONAL LAND SURVEYOR
 COLORADO REGISTRATION NUMBER 18305

NOTICE:
 ACCORDING TO COLORADO STATE LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.



NOTE:
 MAGNETIC NORTH IS CURRENT AS OF 8/11/2015.
 MAGNETIC NORTH CHANGES WEST 0"06' PER YEAR.

NOTES:

- ▲ INDICATES FOUND SECTION CORNER
- INDICATES CALCULATED CORNER
- ELEVATION BASED ON NAVD88 (GEOID09)
- BASIS OF BEARING DERIVED FROM COLORADO COORDINATE SYSTEM 1983 NORTH ZONE UNLESS OTHERWISE NOTED.
- ALL MEASURED DISTANCES ARE GRID. COMBINED SCALE FACTOR: .99972876
- OPERATOR: ROB WILSON / PDOP = 1.2
- SEE ADDENDUM TO WELL LOCATION CERTIFICATE FOR EXISTING IMPROVEMENTS WITHIN 500' OF THE WELL PAD.
- WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.
- THE BOTTOM OF HOLE BEARS S01°04'16"W, 9829' FROM THE HEEL LOCATION.

WELL PAD - PUMA 4C-14HZ

PUMA FED 34N-35HZ
 WELL LOCATION CERTIFICATE
 290' FSL & 616' FWL SWSW (SURFACE)
 LOCATED IN SECTION 23
 268' FNL & 350' FWL NWNW (HEEL)
 LOCATED IN SECTION 26
 465' FSL & 52' FWL SWSW (BOTTOM)
 LOCATED IN SECTION 35
 T1N, R67W, 6TH P.M.
 WELD COUNTY, COLORADO

Kerr-McGee Oil & Gas Onshore L.P.
 1099 18th Street
 Denver, Colorado 80202



CONSULTING, LLC

SHERIDAN OFFICE
 1095 Saberton Avenue
 Sheridan, Wyoming 82801
 Phone 307-674-0609

LOVELAND OFFICE
 1635 Foxtrail Drive, Suite 204
 Loveland, Colorado 80538
 Phone 970-776-4331

DRAFTED BY: LMO	CHECKED BY: BJR	SHEET NO: 1A 1A OF 1
DATE DRAFTED: 8/19/15	DATE SURVEYED: 5/7/15	
REVISED:	FILE NAME: 15-42	

T1N, R67W

N. 1/4 COR.
SEC. 35, T1N, R67W
FOUND 2nd ALUM. CAP
L.S. NO. 25619

MATCH LINE
SEE SHEET 1A

NW. COR.
SEC. 35, T1N, R67W
SET 2nd ALUM. CAP
L.S. NO. 38305

S 89°35'01" W 2643.87' (M)

S 89°36'01" W 2643.74' (M)

NE. COR.
SEC. 35, T1N, R67W
SET 2nd ALUM. CAP
L.S. NO. 38305

SURFACE LOCATION: NAD 83
GROUND ELEVATION= 4991.0'
LATITUDE= 40.030157°
LONGITUDE= -104.865071°
LATITUDE= 40°01'48.564"
LONGITUDE= -104°51'54.254"
HEEL LOCATION: NAD 83
LATITUDE= 40.028624°
LONGITUDE= -104.866017°
LATITUDE= 40°01'43.048"
LONGITUDE= -104°51'57.663"
BOTTOM HOLE LOCATION: NAD 83
LATITUDE= 40.001652°
LONGITUDE= -104.866924°
LATITUDE= 40°00'05.947"
LONGITUDE= -104°52'00.926"

W. 1/4 COR.
SEC. 35, T1N, R67W
FOUND 2nd ALUM. CAP
L.S. NO. 25937

N 00°48'22" W 2640.15' (M)

S 01°04'16" W 9829' GRID
S 01°28'53" W TRUE
S 06°55'44" E MAGNETIC

N 00°39'46" W
2639.74' (C)

35

S 89°35'25" W
1318.63' (M)

S 89°33'40" W
1318.62' (C)

S 89°33'40" W
2638.08' (C)

N 00°32'24" W
5275.85' (M)

CW. 1/16 COR.
SEC. 35, T1N, R67W
FOUND 2 1/2nd ALUM. CAP
L.S. NO. 24307

N 00°46'33" W 2639.14' (M)

2174'
854'

N 00°39'46" W
2638.69' (C)

52'

1265'

2581'

S. 1/4 COR.
SEC. 35, T1N, R67W
SET 2nd ALUM. CAP
L.S. NO. 38305

SE. COR.
SEC. 35, T1N, R67W
FOUND 2 1/2nd ALUM. CAP
L.S. NO. 13482

BOTTOM OF HOLE
465' FSL & 52' FWL

S 89°33'24" W
1316.14' (M)

S 89°34'34" W
1315.90' (M)

S 89°32'41" W 2632.43' (M)

SW. COR.
SEC. 35, T1N, R67W
FOUND ALUM. CAP
NUMBER ILLEGIBLE

W. 1/16 COR.
SEC. 35, T1N, R67W &
SEC. 2, T1S, R67W
FOUND 3 1/4th ALUM. CAP
L.S. NO. 37890

24'37" 8'00"




CERTIFICATE OF SURVEYOR:

THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEY MADE BY ME OR UNDER MY SUPERVISION AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. THIS CERTIFICATE DOES NOT REPRESENT A LAND SURVEY PLAT OR IMPROVEMENT SURVEY PLAT AS DEFINED BY C.S. 38-511-02 AND CANNOT BE RELIED UPON TO DETERMINE OWNERSHIP.

Benjamin J. Reenders
PROFESSIONAL LAND SURVEYOR
8/19/15

BENJAMIN J. REENDERS
PROFESSIONAL LAND SURVEYOR
COLORADO REGISTRATION NUMBER 183305

NOTICE:
ACCORDING TO COLORADO STATE LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THE DATE ON THE CERTIFICATION SHOWN HEREON.



NOTE:
SCALE: 1" = 1000'
MAGNETIC NORTH IS CURRENT AS OF 8/11/2015.
MAGNETIC NORTH CHANGES WEST 0°06' PER YEAR.

NOTES:

- ▲ INDICATES FOUND SECTION CORNER
- INDICATES CALCULATED CORNER
- ELEVATION BASED ON NAVD88 (GEOID09)
- BASIS OF BEARING DERIVED FROM COLORADO COORDINATE SYSTEM 1983 NORTH ZONE UNLESS OTHERWISE NOTED.
- ALL MEASURED DISTANCES ARE GRID. COMBINED SCALE FACTOR: .99972876
- OPERATOR: ROB WILSON / PDOP = 1.2
- SEE ADDENDUM TO WELL LOCATION CERTIFICATE FOR EXISTING IMPROVEMENTS WITHIN 500' OF THE WELL PAD.
- WELL FOOTAGES ARE MEASURED AT RIGHT ANGLES TO THE SECTION LINES.
- THE BOTTOM OF HOLE BEARS S01°04'16"W, 9829' FROM THE HEEL LOCATION.

WELL PAD - PUMA 4C-14HZ

PUMA FED 34N-35HZ
WELL LOCATION CERTIFICATE
290' FSL & 616' FWL SWSW (SURFACE)
LOCATED IN SECTION 23
268' FNL & 350' FWL NWNW (HEEL)
LOCATED IN SECTION 26
465' FSL & 52' FWL SWSW (BOTTOM)
LOCATED IN SECTION 35
T1N, R67W, 6TH P.M.
WELD COUNTY, COLORADO

**Kerr-McGee Oil &
Gas Onshore L.P.**
1099 18th Street
Denver, Colorado 80202



CONSULTING, LLC

SHERIDAN OFFICE
1095 Saberton Avenue
Sheridan, Wyoming 82801
Phone 307-674-0609

LOVELAND OFFICE
1635 Foxtrail Drive, Suite 204
Loveland, Colorado 80538
Phone 970-776-4331

DRAFTED BY: LMO	CHECKED BY: BJR	SHEET NO: 1B 1B OF 1
DATE DRAFTED: 8/19/15	DATE SURVEYED: 5/7/15	
REVISED:	FILE NAME: 15-42	