



WARRIOR ENERGY SERVICES CORP. JOB DATA SHEET

Company ANADARKO Well Name and No. CARMA 13-25 Engineer Jeremy Flores
County Weld Date 1/10/2015 Ticket No. 4495-0183 Unit No. 4495
District Greeley Co. / 0928-200 Line Size 0 Line Length 0
Job Time: 1:00 PM Shop Time: 10:00 AM Leave Shop: 12:15 PM Arrive Location: 12:50 PM
Field Hrs. 1:30:00 Standby Hours: 0:00:00 Total Hours 2:50:00 Travel Time Hrs. 1:20:00
Trip Miles 50 Leave Location: 5:45 PM Arrive Shop: 6:30 PM

Notice: Engineer to monitor for stray voltage prior to rig up: Wellhead volts: 0 Rig volts : 0
Were there any equipment or down hole failures? Yes No If yes explain on Quality Control Analysis Form
Were there any hot shots required? Yes No If yes explain on Quality Control Analysis Form
Were there any personnel problems? Yes No If yes explain on Quality Control Analysis Form
Were there any accidents? Yes No If yes explain on Quality Control Analysis Form
Were there any near misses? Yes No If yes explain on Quality Control Analysis Form

Well Information

Casing Size 4.5 Liner Size 0 Tubing Size Drill Pipe Size
Drill Collar Minimum I.D. Fluid Level 0 Deviation
Max. Temp. Max. Pressure

Run Data

RUN INFORMATION

REMARKS SECTION DESCRIBE RUN DETAILS IN FULL

1 Time in 1:35 PM Out 2:05 PM RIH GR/ JB TO 7200'
From Surface To 7200'
Service Run CCL GR/ JB to 7200'
2 Time in 2:10 PM Out 2:50 PM SET 4 1/2 C.I.B.P. AT 7100'
From Surface To 7100'
Service Set 4 1/2 Casing Plug 7100
3 Time in 3:20 PM Out 3:55 PM Dump Bail 2 sacks of cement on plug at 7100'
From Surface To 7100'
Service Dump Bail Cement on Plug
4 Time in 4:00 PM Out 4:40 PM Set 4 1/2 C.I.B.P AT 7030'
From Surface To 7030'
Service Set 4 1/2 Casing Plug 7030
5 Time in 4:55 PM Out 5:20 PM Dump Bail 2 Sacks of cement on plug at 7030'
From Surface To 7030'
Service Dump Bail Cement on Plug
6 Time in Out
From To
Service
7 Time in Out
From To
Service
8 Time in Out
From To
Service