

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401098202

Date Received:

08/24/2016

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>CHEVRON USA INC</u>	Operator No: <u>16700</u>	Phone Numbers
Address: <u>100 CHEVRON RD</u>		Phone: <u>(970) 675-3814</u>
City: <u>RANGELY</u>	State: <u>CO</u>	Mobile: <u>(970) 697-8385</u>
Zip: <u>81648</u>		Email: <u>mhaub@chevron.com</u>
Contact Person: <u>Micael Haub</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401098202

Initial Report Date: 08/24/2016 Date of Discovery: 08/22/2016 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENW SEC 34 TWP 2N RNG 102W MERIDIAN 6

Latitude: 40.104392 Longitude: -108.828672

Municipality (if within municipal boundaries): _____ County: RIO BLANCO

Reference Location:

Facility Type: FLOWLINE☐ Facility/Location ID No _____☐ No Existing Facility or Location ID No.☒ Well API No. (Only if the reference facility is well) 05-103-09149

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >0 and <1Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 60BBLS of fresh water were released with 0.01BBLS of oil

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Sunny and warmSurface Owner: FEDERALOther(Specify): BLM

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Monday (8/22) at approximately 11:20 am a release occurred from a drained 2" fiberglass line that was being washed with fresh water prior to being capped to be put out of service at Carney 41Y34 (API 05-103-06149) Approximately 60 bbls of potable rinse water and 0.01 bbls of oil were released. Approximately 30 BBLS of water was recovered, and all the oil was recovered. The flush was stopped immediately upon detection. The oil affected area has been water washed. The line will remain out of service until repaired.

List Agencies and Other Parties Notified:

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Micael Haub

Title: HES Specialist Date: 08/24/2016 Email: mhaub@chevron.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401098206	SITE MAP
-----------	----------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)