

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2016

Submitted Date:

11/29/2016

Document Number:

666802761**FIELD INSPECTION FORM**

Loc ID 334742 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General | | cogcc.inspections@encana.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------------|-------------|
| 256759 | WELL | PR | 12/12/2003 | GW | 045-07497 | MILLER 14-2 | PR |
| 273453 | WELL | PR | 11/11/2010 | GW | 045-10248 | CEDAR SPRINGS RANCH 11-14D (B14W) | PR |
| 273454 | WELL | PR | 02/03/2005 | OW | 045-10247 | CEDAR SPRINGS RANCH 11-15D (B14W) | TA |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| Type | Area | Volume |
|------|------|--------|
| | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

3

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

2

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tanak ID | SE GPS |
|----------|---|----------|-----------|----------|--------|
| METHANOL | 1 | OTHER | STEEL AST | | , |

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents | # | Capacity | Type | Tanak ID | SE GPS | |
| CONDENSATE | 2 | OTHER | STEEL AST | | 39.449739,-107.741624 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Paint | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | 250bbbs | | | | | |
| Other (Type) | | | | | | |
| Berms | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Metal | Adequate | Walls Sufficent | Base Insufficient | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Venting: | | | | | | |
| Yes/No | NO | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Flaring: | | | | | | |
| Type | | | | | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Inspected FacilitiesFacility ID: 256759 Type: WELL API Number: 045-07497 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 273453 Type: WELL API Number: 045-10248 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 273454 Type: WELL API Number: 045-10247 Status: PR Insp. Status: TA**Idle Well**Purpose: ☐ Shut In☒ Temporarily Abandoned

Reminder: _____

Comment: No form 4 on file to continue Temporarily Abandoned wellCorrective Action: Contact COGCCDate: 12/27/2016

| Environmental | |
|-----------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): NO | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | | | | | |
| | | Gravel | Pass | | | |
| Gravel | Pass | | | | | |
| | | Culverts | Pass | | | |
| | | Ditches | Pass | | | |
| Ditches | Pass | | | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT