

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2016

Submitted Date:

11/30/2016

Document Number:

682401552**FIELD INSPECTION FORM**
 Loc ID 445209 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445203	WELL	XX	03/19/2016		123-42948	Holliday Federal LC23-785	CI
445204	WELL	XX	03/19/2016		123-42949	Holliday Federal LC23-775	CI
445205	WELL	XX	03/19/2016		123-42950	Holliday Federal LC23-780	CI
445206	WELL	XX	03/19/2016		123-42951	Tombstone Federal LC23-765	CI
445207	WELL	XX	03/19/2016		123-42952	Tombstone Federal LC23-760	CI
445208	WELL	XX	03/19/2016		123-42953	Tombstone Federal LC23-755	CI

**General Comment:**

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401152468. Stormwater and erosion control BMPs need to be installed prior to the start of construction.

**Location Construction**

Location ID: 445203 CDP: \_\_\_\_\_

Comment: Stormwater or erosion control BMPs were not installed prior to construction. After making a previous call to the operator regarding a location ~ ¼ mile to the west that did not have stormwater or erosion control BMPs, a BMP was installed during this inspection; therefore, no formal corrective action was issued.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Form 2A COAs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

SLOPE ROUGHENING	Yes		
------------------	-----	--	--

Comments: Erosion BMPs: Surface roughening, which is a temporary BMP, was installed during this inspection.

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: Refer to attached inspection photos in Document #682401553.

Corrective  
Action:

Date: \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: <u>445203</u>	Type: <u>WELL</u>	API Number: <u>123-42948</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445204</u>	Type: <u>WELL</u>	API Number: <u>123-42949</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445205</u>	Type: <u>WELL</u>	API Number: <u>123-42950</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445206</u>	Type: <u>WELL</u>	API Number: <u>123-42951</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445207</u>	Type: <u>WELL</u>	API Number: <u>123-42952</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>445208</u>	Type: <u>WELL</u>	API Number: <u>123-42953</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401552	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017323">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017323</a>
682401553	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016963">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4016963</a>